# ARTICLE 342 ACCIDENT Pilot's & Witnesses' Statements



CHANGE-A

TOP SECRE

ARTICLE 342 ACCIDENT

HOW CLOSE WAS HE?

	Pilots & Witnesses' Statements
	A/C 342 ACCIDENT is changed as follows:
	1. Page 40, line 6, after WHEN I WAS INITIALLY CHECKING OUT, add: AND I WOULD GO
† * * *	BACK IN THE BACK AND WATCH IT. BUT YOU REALLY WOULDN'T SEE THE WING FLEX FROM
*	LOOKING AT HIM DIRECTLY BACK IN THE BOOM POSITION. THE WING FLEXING YOU WOULDN'T
	NOTICE SO MUCH THERE AS WHERE YOU ARE LOOKING - HE WAS RIGHT AND LEVEL WITH MY
25X1A	
25X1A	THIS IS IN LEVEL FLIGHT.
25X1A	YES SIR.
† •	IFP PIK.
	SO IN LEVEL FLIGHT THERE MUST HAVE BEEN SOME MINOR TURBULENCE THERE. MAYBE YOU
25X1A	
	DIDN'T FEEL THE TURBULENCE?
25X1A	THE WAS SMOOTH AS IT COULD BE
	' I WOULD SAY IT WAS SMOOTH, IT WAS SMOOTH AS IT COULD BE.
	DE COME DESCON FOR THE FIFYING OF THE WING.
	BUT WHAT I WAS SAYING THERE MUST BE SOME REASON FOR THE FLEXING OF THE WING.
25X1A	EITHER TURBULENCE OR A MANEUVER. WAS HE ACTUALLY MANEUVERING WHEN YOU NOTICED
	THE FLEX?
25X1A	- HOLDEN HELDEN HER HELDEN HER HELDEN HELDEN HELDEN HELDEN HELDEN HELDEN HELDEN HELDEN HELDEN
20/(1/(	NO SIR. HE WAS FLYING FORMATION. HE WAS ACTUALLY HOLDING FORMATION WITH ME.
25X1A	
23X1X	THEN IT WAS THE LEFT WING YOU SAW FLEXING?
); )EV4.4	
25X1A	YOU COULD SEE BOTH WINGS FLEXING.

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

Approved For Release 2002/06/18 : CIA-RDP38800447R000100010065-0

083X

	25X1A <sub>ci</sub>	HANGE-A
--	---------------------	---------

## TOP SECRE

25X	11/	١

I WOULD SAY THAT HE WAS 200 FEET OFF THE TIP OF MY WING.

THEN THERE WAS NO CHANCE OF YOUR WING AFFECTING HIM?

2. Page 40, line 14, after PUSHING VERY MUCH AIR OUT, add: THAT FAR. NOW IF IT WAS HIGHER, IF I WAS FLYING AT A HIGHER AIR SPEED I COULD SEE THAT BOW WAVE

25X1A

EFFECT YOU MIGHT GET.

C

COULD YOU ESTIMATE HOW MANY MINUTES IT WAS FROM BREAKAWAY TO THE TIME FROM LEVEL

25X1A FLIGHT HE STARTED CLIMB?

WELL WE BROKE AWAY, I DON'T KNOW IF THE NAV LOGGET IT, I DON'T HAVE ANY PRECISE

TIME BUT I WOULD GUESS FROM THE TIME HE BROKE AWAY UNTIL HE WAS BACK IN POSITION-2 OR 3 MINUTES.

Approved For Release 2002/06/18 : CIA-RDP74P00447R000100010065-0

### Approved For Release 2002/06/18 CCA-RDP74B00447R000100010065-0 Page 1

#### PILOT'S STATEMENT

25X1A	A/C 342 ACCIDENT
	GENTLEMEN, WE ARE ALL GATHERED HERE FOR THE STORY AS
25X1A	TOLD BY THE PILOT, ON THE ACCIDENT TODAY 25X1
	ON A/C 342, WHICH OCCURRED TODAY DURING REFUELING.
	WHAT WE'LL PROBABLY DO IS JUST START OFF WITH YOUR STORY
25X1A	AND THEN AND I CAN FILL IN WHAT WE SEEN
	AFTERWARDS SO IF YOU JUST GO RIGHT AHEAD FROM THE BEGINNING
	TO THE END AND TELL US YOUR COMPLETE STORY OF IT.
25 <u>X1</u> A	
	WELL - RATHER - I DON'T THINK THERE WAS ANYTHING TO - EVERY-
	THING WAS NORMAL THRU THE REFUELING. YOU DON'T FEEL THERE
25X1A	WAS ANYTHING WORTH GOING INTO THERE DO YOU?
	NO I'VE ALREADY TOLD THE LOCKHEED PEOPLE MY STORY ABOUT

THE DRY HOOKUP AND SO ON. SO THEY'VE GOT MOST OF THAT.

25X1A

EVERYTHING WAS QUITE NORMAL AND IN FACT IT WAS EXCELLENT. EVERYTHING WAS WORKING REAL FINE. AND WE COMPLETED WITH THE BREAKAWAY AND I PULLED OFF TO THE RIGHT, UP AND UP NEXT TO THE 135 AND WAS TALKING WITH THOSE FELLOWS AND I WAS GOING TO PULL OFF AND COME HOME. IT WAS ABOUT 10:20 AND WE WANTED THE AIRPLANE ON THE GROUND BY 10:30. AND I LOOKED DOWN AND I HAD ABOUT 210 KNOTS. I WAS IN GUST AND I RECALL THE SPEED BRAKES WERE IN. I JUST PULLED OFF AWAY FROM THEM WHICH I HAD DONE MANY TIMES WITH 210 KNOTS AND STARTED TO SHAKE A LITTLE BIT AND EVEN BEFORE I COULD TAKE ANY ACTION AT ALL IT JUST-IT SHULDERED - IT CAME APART. AND THEN I - I DON'T KNOW WHAT COME OFF YOU COULD PROBABLY TELL BETTER THAN I - BUT IT WAS JUST A SLIGHT SHUDDER AND THEN ALL OF A SUDDEN IT LUNGED FORWARD - IT FELT LIKE IT LUNGED FORWARD AND JUST CAME A FALLEN - IT WAS JUST - OR TUMBLE - IT FELT LIKE IT WAS TUMBLING AND THEN I PLAYED WITH THE YOKE TO SEE IF I HAD ANY CONTROL AND I FELT LIKE I HAD SOME. A LITTLE - BUT NOTHING THAT I COULD RIGHT IT WITH AND I LOOKED OUT AND I HAD NO WING AT LEAST ON THE RIGHT. BACKGROUND VOICE - "RIGHT WING".

RIGHT WING WAS GONE, I DIN'T EVEN LOOK FOR THE LEFT ONE. I JUST LOOKED OUT AND SAW THE RIGHT WING WAS GONE. I KNEW I WAS GOING TO HAVE TO GET OUT, SO I - IT WAS - IT REALLY WASN'T VERY VIOLENT, REALLY I WAS QUITE SURPRISED CAUSE I'VE HEARD SEVERAL STORIES ABOUT HOW VIOLENT IT GETS -IT GETS YOU ON YOUR BACK AND THROWS YOU AROUND. I WAS CONSCIOUS THRU THE WHOLE THING - MADDER THAN HELL CAUSE I COULDN'T CONTROL IT AND FINALLY DECIDED THAT I WAS GOING TO HAVE TO GET OUT, THERE WASN'T ANY OTHER ALTERNATIVE. SO I PUT THE FEET IN THE STIRRUPS AND ASSUMED THE PROPER POSITION AND AMAZINGLY ENOUGH I REACHED FOR THE T BIRD TO EJECT - REACHED FOR THE T BIRD HANDLE FIRST AND GRABBED BOTH HANDLES LIKE THAT AND THEN REALIZED IT WAS WRONG AND I NEVER DID SEE ANY INSTRUMENTS OR SPEEDS OR INDICATIONS WHEN I WAS TUMBLING - IN FACT I TRIED TO CALL BEFORE I STARTED TO GET OUT. I WENT TO MAKE A TRANSMISSION AND THERE WAS NONE - IT WAS DEAD. APPARENTLY, UNLESS YOU HEARD IT I DON'T THING ANYONE HEARD ANY OF IT. I PULLED THE HANDLE AND IT WAS THE LONG WAIT AND THE CANOPY WENT OFF AND THEN IT FIRED ME OUT AND IT WAS NOTHING WORSE THAN A GOOD SOLID FOOTBALL TACKLE. IT FELT TO ME. - JOLT BUT THAT WAS ALL AND I WAS OUT AND I COULD FEEL THIS - I COULD SORTA COULD FEEL THE SEAT LEAVE AND THEN, YOU KNOW THAT NICE QUIET SOFT FEELING UP THERE AND FLOATED DOWN. I PLAYED A LITTLE SKYDIVING ROUTINE

TO SEE IF I COULD SKYDIVE AND THEN I REALIZED I WAS GOING TO HAVE TO CHECK AND THEN I WAS BECOMING CONFUSED AS TO WHETHER I HAD MY DOG SNAP HOOKED OR NOT AND OBVIOUSLY IT WASN'T HOOKED AND SO THEN I, YOU KNOW HOW YOU CONFUSE AT ALTITUDES AS WHERE YOU ARE - HOW HIGH YOU ARE FROM THE GROUND SO I PULLED THE D-RING - GRABBED THE D-RING AND PULLED IT AND GOT A BIT OF A JOLT AND IT BLOSSOMED AND I DON'T KNOW WHAT ALTITUDE I WAS BUT IT WAS AWFULLY COLD UP THERE - MY HANDS GOT REAL COLD. AND THE THING WAS ROCKING A LOT AND JUST BEFORE 2 or 3,000 FEET I PULLED THE SURVIVAL KIT GEAR AND RELEASED IT AND THAT ISN'T TOO GOOD A - I DON'T KNOW WHETHER IT'S A GOOD IDEA OR NOT - IT SWINGS AN AWFUL LOT - MAYBE IT WAS THE WIND BUT IT WAS SWINGING PRETTY BAD AND SWINGING ME AND CONSEQUENTLY GIVING ME A LOT OF SWING THAT I DIDN'T HAVE PRIOR TO RELEASING THAT THING AND THEN I WENT THRU THE CLOUD DECK. THEN OF COURSE I PLAYED AROUND WITH THE RISERS SOME BUT FOUND THAT I COULDN'T CONTROL IT TO MY SATISFACTION AT LEAST. SO THEN I STARTED SEEING THE GROUND COMING SO I JUST ASSUMED THE PROPER POSITION AGAIN AND WAITED AND I HIT GOING BACKWARDS AND HIT MY FEET JUST RIGHT. AND ON MY BUTTOCKS AND MY HEAD. AND I HAD RELEASED THE RISERS HERE CAUSE I WAS AFRAID WE'D

HAVE THE WIND THAT THEY FORECASTED HERE AND IF I HAD THE WIND UP IN THE MOUNTAINS I WOULD WANT TO GET OUT OF THAT. AND I PULLED THE TWO RISERS JUST AS I HIT -- MY RELEASE HANDLES AND THE CHUTE WAS A BIT BLOSSOMED - KINDA HALF BLOSSOMED AND IT FELL AS SOON AS I RELEASED THE RISERS -IT FELL DOWN - WELL - I WAS A BIT SHOCKED AND GOT MY BREATHE AND SAW YOU GUYS AND WAVED AT YOU AS YOU WENT BY AND THEN I WENT AND GOT MY SURVIVAL GEAR OUT AND ONE OUT OF THE PARACHUTE FIRST AND I TURNED THAT THING - WHAT I THOUGHT TURNED IT ON - SOMEBODY TOLD ME IT WAS ON AUTOMATICALLY BUT I TURNED IT ON - AND THEN I WENT AND GOT MY UH GUARD CHANNEL C4 TYPE TRANSMITTER AND I TRIED TRANSMITTING AND I WAS TALKING TO THE TANKER BUT EVERYTIME HE TRIED TO TRANSMIT TO ME MY SQUEAL FROM THAT FIRST ONE WAS COMING THRU AND I COULDN'T HEAR HIM - AND I FINALLY REALIZED WHERE THE SQUEAL WAS COMING FROM AND GOT IT OFF. AND THEN I MOVED UP TO A CLEARING. BUT THE HELICOPTER COULDN'T COME IN THERE SO THEN HE CAME ON IN FURTHER DOWN - WE HAD LARGER CLEARING - AND THEY CAME OUT AND MET ME ABOUT HALFWAY - WE PICKED UP THE SURVIVAL GEAR AND CAME HOME. THAT FROM BEGINNING TO END.

25X1A

I MIGHT JUST MENTION THAT TOM AND I WERE IN THE T BIRD FLYING OFF I'D SAY ABOUT 2 MILES TO THE EAST OF THE KC135 AND THE U2 AND WE SEEN THIS WHEN IT HAPPENED AND THE TANKER ALSO TRANSMITTED THAT THE WING HAD COME OFF AND THEN WE LOOKED FOR YOU, I GUESS - IT SEEMED LIKE A LONG TIME - BUT I IMAGINE AT LEAST A MINUTE AND A HALF OR TWO MINUTES BEFORE WE SEEN YOUR PARACHUTE. DURING THIS TIME WE WERE LOOKING AND PROBABLY IN A DESCENT - I NEVER DID CHECK MY ALTIMETER - WE SEEN YOUR PARACHUTE OPEN - WE SEEN IT OPENED - I DON'T REALLY KNOW WAHT ALTITUDE THIS WAS - A WING WAS BELOW YOU IN A KINDA OF A OSCILLATING ARRANGEMENT. THE HEIGHTS OF THE CLOUDS WAS 8,000 FEET - THE TOPS OF THE CLOUDS WERE 8,000 FEET AND WE SEEN DEAK WHEN HE PULLED HIS SURVIVAL EQUIPMENT AND WE SEEN IT DEPLOYED BELOW HIM AND THEN ALMOST IMMEDIATELY HE WENT INTO THE CLOUDS SO I'D SAY YOU PULLED AT MAYBE 2,000 FEET ABOVE THE CLOUDS OR SO - YOU WERE OSCILLATING - THE PARACHUTE - YOU WERE JUST GOING BACK AND FORTH LIKE THIS ALL THE WAY DOWN.

25X1A

YEAH, YEAH, IN FACT I GOT, WAS GETTING SICK.

SAY THAT THE WING HAD COME OFF. I DON'T KNOW IF TOM HAD SEEN

WHICH WING IT WAS FOR SURE OR NOT.

25X1A \_\_\_\_\_\_.

NO IT SEEMS TO ME THE TANKER DID SAY THAT IT WAS THE RIGHT WING, HOWEVER, I'M NOT SURE ABOUT THAT - I DO REMEMBER THAT HE MENTIONED THE WING HAD COME OFF AND THAT THE AIRPLANE HAD DISCENTEGRATED. THAT WAS HIS COMMENT.

25X1A

AS I SAID I FELT WHEN THIS THING JOLTED ON ME AND KINDA JUST
WENT ALL TO PIECES - IT SEEMED LIKE - YOU KNOW - I MEAN IT JUST
STARTS THROWING YOU AROUND A LITTLE BIT AND I GRABBED THE
YOKE AND STARTED PLAYING WITH IT TO SEE IF I HAD ANY CONTROL
AND I FELT LIKE I STILL HAD TAIL AND I'VE BEEN THINKING ABOUT IT
SINCE AND I THOUGHT I'D ALWAYS HEARD THAT THE TAIL COMES OFF
BUT OF COURSE I DON'T KNOW - YOU SAID I'M INTERESTED TO SEE
WHETHER THE TAIL WAS STILL INTACT AS WHICH CAME OFF FIRST.

25X1A

I THINK WHAT WE COULD DO IS CALL THOSE PEOPLE UP AT BEALE
TODAY AND THEY MUST HAVE HAD A GOOD OBSERVER BECAUSE
WHOEVER IT WAS,ALMOST AT THE SAME TIME I SEEN THIS HAPPENING.
I HEARD HIM CALL ON THE RADIO THAT THE WING HAD COME OFF.

	QUESTION: -
	IT MUST HAVE BEEN THE BOOM GUY THEN HUH?
25X1A	EITHER THE BOOM OR
25X1A	NO, I THINK IT WAS THE COPILOT. I WAS ON THE COPILOTS SIDE.
25X1A	YOU WERE UP FORWARD, THAT'S RIGHT?
25X1A	I PULLED UP ON THE RIGHT SIDE OF THE AIRPLANE AND THEN I PULLED OFF LIKE THIS.
25X1A	IS THERE ANY TURBULENCE AT ALL IN THERE?
25X1A	NO THERE WAS NO TURBULENCE VERY LIGHT IF ANY. IT WAS NOT
	NOTICEABLE.

25X1A

THIS WAS AT 35,000 FEET AND THE TANKER WAS HOLDING 200 KNOTS AND AT TIMES HE WAS A LITTLE BIT BELOW THIS - 197. WE BOTH REMARKED ABOUT IT AT ONE TIME SO I DON'T THINK AT ANY TIME HE EVER GOT ABOVE 200 KNOTS DURING THIS REFUELING - HE WAS REAL GOOD AT THAT.

NOW TO GO ON FROM HERE, MAY WE JUST START IN WITH ANYBODY
FROM THE LOCKHEED PEOPLE WHO HAVE SOME QUESTIONS AND THEN
LET LIFE SUPPORT GO IN FROM THERE.

25X1A

I'D LIKE TO ESTABLISH POSITION POSSIBLY A LITTLE BETTER. YOU WERE - YOU SAY YOU WERE IN THE COPILOT POSITION YOU WERE

25X1A

25X1A

YEAH.

AND A LITTLE HIGH?

OUTBOARD OF THE RIGHT-HAND WING.

25X1A

YES. CAN ASSURE YOU I WASN'T - I DON'T THINK ANYTHING TO DO WITH THE JETWASH OR FROM HIS JETWASH OR WING WASH. I WAS

#### Approved For Release 2002/06/183 CIA-RDP74B00447R000100010065-0 Page 11

	WAY OUT TO THE RIGHT SIDE AND FORWARD OF HIM. ACTUALLY, I	
	MEAN THEY CAN GIVE YOU THE SAME STORY - I MEAN I WAS WAY OUT	
	AND FORWARD OF HIM AND, YES - THAT ANSWERS YOUR QUESTION.	
25X1A		
	DID YOU NOTICE OR HAPPEN TO NOTICE EITHER THEN OR A SHORT	
25X1A	TIME PRIOR TO THAT WHAT YOUR FUEL COUNT WAS?	
	YES, IN THE 400's - IT WAS IN THE 400's. AND THAT WAS	
25X1A	I THOUGHT YOU SAID IT WAS IN THE 200 GALLONS ABOUT WHEN YOU LOOKED AT IT AND STARTED DOWN?	
25X1A	NO I NEVER MADE ANY STATEMENT ON FUEL, I DON'T BELIEVE TOM.	
25X1A	JUST A FEW MINUTES AGO I THOUGHT YOU MENTIONED HOW YOU HAD	
	LOOKED TO SEE WHAT YOUR FUEL STATE WAS, 25X	ΙA

25X1A	
	NO I THINK I SAW 400, ONE TIME - THAT WAS WHEN I WAS ON THE
	TANKER AND I WAS CHECKING WHEN WE WERE WORKING TO SEE WHEN
	I WAS COMING BACK.
	COMMENT: -
	690. PROBABLY LESS THAN THAT THOUGH.
	QUESTION: -
	FULL AUXILIARY TANKS?
25X1A	
25X1A	YEAH.
	-
	WHEN IT HAPPENED YOU FELT SOMETHING CAME LOOSE BUT YOU
	DIDN'T SEE WHAT IT WAS?
25X1A	
	NO - NO IT WAS A BIT OF A SHUDDER AND THEN I JUST FELT MYSELF
25X1A	BEING FLUNG IN THE COCKPIT - I SAW NOTHING.
	DO YOU HAVE ANY FEEL FOR THE DIRECTION OF BOTATIONS

25**X4**A

NO - ONLY I FELT LIKE THE NOSE WENT DOWN ON ME. BUT I SEEMED
TO STAY KINDA UPRIGHT I WAS NEVER ON MY BACK - AND IN THE
EARLY PARTS OF IT I WAS NEVER ON MY BACK BUT WHEN I DID FINALLY
GET ON MY BACK I FELT LIKE I WENT OVER FORWARD ON MY BACK IN OTHER WORDS I DIDN'T ROLL.

25X1A

YOU STAYED THAT WAY? NOT ON YOUR BACK IN A NOSE

DOWN POSITION FOR AWHILE AND THEN YOU ROLLED OVER?

25X1A

YEAH I THINK I FELT LIKE I WAS THROWN FORWARD AND THEN I THINK
I WAS KINDA DOING A LEAF, YOU KNOW, QUICK, FAST JERK AROUND
LIKE THIS TYPE OF THING AND THEN I FELT MY - THEN IT FELT LIKE
IT GOT PROGRESSIVELY WORSE. IT WAS GETTING PROGRESSIVELY
WORSE AND THEN I RODE IT INTO THAT FOR AWHILE AS IT WAS ROUGH,
TO SEE IF IT WAS GETTING - WHERE I WAS - IN WHAT POSITION AND SO
FORTH. AND IT DIDN'T GET ANY WORSE - IN OTHER WORDS IT JUST GOT
SO BAD WHERE IT WAS KINDA THROWING ME AROUND A LITTLE BIT KINDA JERKING ME AROUND AND IT NEVER GOT ANY WORSE THAN THAT.

25X1A

THE TUMBLE THAT YOU REFERRED TO WAS, AS FAR AS YOU CAN
RECALL, JUST FLIPPING OVER ON YOUR BACK ONCE AND THEN FROM
THERE IT WAS A MOTION IN MOST ANY DIRECTION?
Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

47 19 19 7

YES. NOW I'M NOT SAYING I FLIPPED - ORIGINALLY RIGHT ON MY BACK I KINDA FELT LIKE I WAS UPRIGHT UP AT THE FIRST. WHATEVER IT WAS DOING, I TOLD MIKE I WAS IN PRETTY GOOD FLYING POSITION -THAT I HAD LOST PART OF IT BUT NOT ALL OF IT. AND I FELT LIKE I COULD - I DIDN'T HAVE FULL CONTROL, YOU KNOW - I WAS STILL KINDA UPRIGHT AND I COULD LOOK AROUND AND STILL HAD A HORIZON. AND I LOOKED OUT AND MY WING WAS GONE.

QUESTION: -

YOUR RIGHT WING?

25X1A

THE RIGHT WING - I LOOKED OUT AND SAW A RIGHT WING GONE AND THEN I KNEW.

QUESTION: -

WERE YOU IN A CLIMBING TURN, DID YOU SAY?

25X1A

YES.

QUESTION: -

YOU WERE, AT THE TIME THIS OCCURRED - IT INITIALLY OCCURRED WHEN YOU WERE IN A CLIMBING RIGHT TURN?

25X1A	
	YES - A RIGHT CLIMBING TURN.
25X1A	
	ALSO, YOU WERE PROBABLY ABOVE THE TANKER AT THAT TIME WERE
	YOU NOT?
25X1A	
	OH, YES - LIKE I SAY, I FEEL CERTAIN AND I'M SURE THE TANKER WOULD
	AGREE THAT I WAS NEVER IN THEIR JETWASH OR ANYWHERE NEAR
	THEM - IN OTHER WORDS I DON'T BELIEVE IT WAS INDUCED BY THUM
	AT ALL BY THEIR JET - I WAS TO THE RIGHT AND ABOVE THEM
	PRETTY MUCH PULLING OFF TO THE RIGHT.
25X1A	
	COULD YOU GUESS APPROXIMATELY WHERE THE WING WAS GONE?
	DID YOU SAY YOU DIDN'T SEE ANY WING AT ALL AND -
25X1A	
25X1A	NAH I JUST LOOKED OUT AND NO WING.
	NO WING AT ALL 2

QUESTION: -

WERE YOU APPLYING ANY AILERON AT THE TIME?

25X1A

YEAH, A LITTLE. I WAS THROWING A LITTLE AILERON AND COMING BACK A LITTLE BIT.

I'D LIKE TO SAY, YOU KNOW THAT, NO I WOULDN'T LIKE TO SAY THAT
I INDUCED IT BUT FOR YOUR BENEFIT TO SAY WHAT HAPPENED, YOU
KNOW, I JERKED IT INTO THIS THING, BUT I'VE USED THIS MANEUVER
MANY TIMES IN THE SAME POSITION, IN OTHER WORDS YOU KNOW,
AND I'VE ALSO PULLED IT MUCH MORE ON TAKEOFF, YOU KNOW,
WHEN WE'RE PULLING UP ON TAKEOFF - I FEEL A LOT MORE PRESSURE
ON TAKEOFF THAN I FELT WITH THIS.

QUESTION: -

25X1A

YOU WERE STILL IN GUST AT THE TIME?

YES, I WAS IN GUST. I HAD NEVER SHIFTED. I HAD BEEN IN GUST RIGHT AFTER TAKEOFF.

NOW, MIKE, I GUESS I SAID THE EQUIPMENT AS FAR AS THE EJECTION, CANOPY AND EVERYTHING WORKED JUST BEAUTIFULLY - JUST LIKE IT WAS SUPPOSED TO. AND OF COURSE THERE HAS ALWAYS BEEN SOME DOUBT AMONG OUR MINDS, I THINK, THAT THIS SYSTEM IS SUPPOSED TO WORK BUT IT NEVER DOES, YOU KNOW WHAT I MEAN, WE'VE HAD SEVERAL INCIDENTS WHERE GUYS HAVE GONE IN WITH THE AIRPLANE FROM ALTITUDES - WE ARE ASSUMING THAT THE AIRPLANE HAD BROKEN UP AND THEY DIDN'T GET OUT OF IT. OR AT LEAST THE SEAT DIDN'T WORK, YOU KNOW.

25X+A

DURING YOUR EJECTION, YOU DIDN'T FEEL ANY EXCESSIVE G FORCES
THAT WOULD DISRUPT THE EQUIPMENT - IT WAS PRETTY MUCH A
FAIRLY STANDARD TYPE EJECTION - YOU LEFT OTHER - NOT
EXTREMELY ADVERSE CONDITIONS, LET'S PUT IT THAT WAY.

25X1A

NO, NO I WOULDN'T CONSIDER IT - NO I WASN'T BEING THROWN

AROUND WHERE I COULDN'T ACTUALLY CONTROL MYSELF AND I

DON'T BELIEVE THAT I WAS UPSIDE DOWN BECAUSE I COULD - I

ACTUALLY COULD ACTUALLY MANLUVER AND PUT MY FEET IN THERE

AND I COULD ACTUALLY PUT MY HANDS TO THE SIDE AND MANEUVER

	MY HANDS. I'VE HEARD THAT WHEN YOU GET UPSIDE DOWN, GET
	AN AWFUL LOT OF G FORCES THAT YOU CAN'T - YOU HAVE TO WORK
	YOUR HANDS DOWN TO GET A HOLD OF THE EJECTION HANDLE AND
	THIS TYPE OF THING.
25X1A	
	DO YOU FEEL YOU WERE UPRIGHT WHEN YOU EJECTED?
25X1A	
	I DO - YES IN FACT, I CAN'T REALLY SAY I WAS EVER ON MY BACK
	MAYBE PART WAY, YOU KNOW PART OF THE SPIN MAYBE.
25X1A	
_	WERE YOU THROWN TO THE SIDE OF THE COCKPIT?
25X1A	<del></del>
	YES - I WAS KINDA BEING THROWN BOTH WAYS.
25X1A	-
	YOU DIDN'T HEAR ANY BANG OR ANYTHING PRIOR TO THIS VIBRATION -
	INITIAL VIBRATION - SHUDDER?
25X1A	
	IT ALL HAPPENS PRETTY QUICK, JOHN.
25X1A	
23/ I/	_

2	5	X	1	Α
_	_			• . •

YEAH, A SLIGHT SHUDDER, "CH-CH-CH", AND THEN "BANG", "WHAM",
AND THEN EVERYTHING JUST - SICKENING FEELING AND THEN YOU'VE
GOT NO MORE CONTROL. AND IT WASN'T A BAD SHUDDER, YOU KNOW,
WHAT I MEAN, IT WASN'T ONE OF THESE FULL STALL SHUDDERS AND
THIS TYPE OF THING IT WAS - AND I MENTION IT ONLY BECAUSE IT
WAS SLIGHTLY NOTICEABLE, THAT'S ALL.

DO YOU HAVE ANY OTHER QUESTIONS, LOCKHEED?

25X1A

25X1A

25X1A

THIS WAS A LOW LEVEL FLIGHT SO IT IS GOING TO BE
VERY SHORT - I GOT MOST OF THE QUESTIONS I NEED. DID YOU MAKE
ANY PREPARATION FOR BAILOUT OTHER THAN THE ONE TO BAILOUT
POSITION AND PULL THE D-RING SUCH AS DISCONNECT ANY COMMUNICATION CORD, PULL DOWN YOUR HELMET, VISER, OR ANYTHING
EXCEPT --

25X1A

NO. NO I DIDN'T PULL THE VISER, ON MY WAY DOWN I TRIED MY CHIN STRAP AND MADE SURE I HAD MY HELMET WHEN I HIT.

25X1A	
	YOU HAD NO PROBLEM WITH ANYTHING GOING OUT, DO YOU REMEMBER
•	IF YOU HIT ANYTHING IN THE SEAT EJECTION SUCH AS THE CANOPY OR
	CAN YOU RECALL ANYTHING THAT YOU WOULD HAVE HIT?
25X1A	NO. I GOT THESE BRUISES ON MY KNEES AND LEGS RIGHT SIDE. I
	DON'T KNOW. AND IT WASN'T FROM LANDING ON THE GROUND, I'M
	SURE.
J	SO IT'S IN THE PROCESS OF GETTING OUT, OR BANGING AROUND THE AIRPLANE.
25X1A	
25X1A	YOU HAD REMOVED YOUR LOW LEVEL LANYARD ON THE WAY UP?
25X1A	YES.
25X1A	AND YOU HAD YOUR OXYGEN MASK ON?
	YES.

25X1A	-
	DID YOU HAVE ANY TROUBLE
25X1A	
25X1A	I HAD ALSO REMOVED THE LITTLE PIN.
	THE SEAT PACK PIN WAS REMOVED BEFORE EJECTION?
25X1A	
	YEAH BEFORE TAKEOFF AND I HAD LEFT IT OUT.
25X1A	
•	HAD YOU DISCONNECTED YOUR LOW LEVEL LANYARD?
25X1A	
25X1A	YES ON THE WAY UP. D-RING?
25X1A	RIGHT. CONTINUES: - DID YOU HAVE ANY TROUBLE SEPARATING
	YOURSELF AND THE SEAT PACK FROM THE SEAT ITSELF? OR DID IT
	JUST SEEM TO BE GONE?
25X1A	
	NO WHEN I SQUEEZED IT, IT FELL RIGHT DOWN.

25XTA	-
	AND AFTER YOU EJECTED THOUGH, WAS THE SEAT JUST GONE? DID
	YOU HAVE TO PULL YOURSELF AND THE PACK OUT?
25X1A	
	NO - I JUST SORTA FELT IT LEAVING ME. I DIDN'T CONSCIOUSLY DO
	ANYTHING TO GET RID OF THE SEAT - NO.
25X1A	
	DID YOU HAVE ANY PROBLEM REACHING ANYTHING SUCH AS YOUR
,	D-RING, OR YOUR SEAT PACK HANDLE WHEN YOU RELEASED IT?
25X1A	
	NO, SEAT PACK HANDLE IS QUITE HANDY, VERY NICE BECAUSE OF
	THOSE ANTI-FLAIL STRAPS I'M SURE.
25X1A	
	DID YOU READILY FIND YOUR RIP CORD?
25X1A	
ZONIA	I HAD A BIT OF TROUBLE BECAUSE OF COURSE THE TWO PARACHUTES
	WE FLY ARE DIFFERENTLY AND YOU'RE A BIT CONFUSED AND I
	REACHED THE WRONG PLACE THE FIRST TIME. I REACHED OVER
	HERE. AS SOON AS I DIDN'T FIND IT, I KNEW WHERE IT WAS.

25X1A	
	AND YOU MANUALLY PULLED UP YOUR TIMER AND DIDN'T ACTIVATE
25X1A	
	NO I MANUALLY PULLED IT. IT WAS AWFULLY HARD TO SIT THERE
	AND WAIT. AWFULLY HARD! ESPICALLY WHEN YOU'RE OVER
	MOUNTAINS.
25X1A	
	FOR YOUR INFORMATION AS YOU KNOW, IT WOULD HAVE AUTOMATICALLY
	OPENED AT 14.000.
25X1A	
	I KNOW.
25X1A	<del>-</del>
	AND EVERYTHING YOU DID WAS SO CORRECT ON RELEASE OF THE PARA-
	CHUTE CANOPY ITSELF IN FIGURING ON THIS WIND, DID YOU RELEASE
	YOUR GUARDS FOR THE CANOPY RELEASES ON THE WAY DOWN?
25X1A	
	YEAH AS'I WENT THROUGH THE CLOUD LAYER AND AS I COULD SEE THAT
	I WAS COMING UP TO THE GROUND PRETTY RAPIDLY AND I RELEASED
	IT_THE TWO GUARDS.

25 <b>X4</b> A	
	AND WHEN YOU TOUCHED THE GROUND YOU RELEASED BOTH CANOPIES?
25X1A	
	YEAH AND IT WAS STILL - THEY RELEASED BUT THEY WERE STILL
	CONNECTED TO ME THROUGH THAT RADIO CORD, YOU KNOW, THAT
	RUNS UP THROUGH THE RISER AFTER I FINALLY - AND IT WAS KINDA
	HALF BLOSSOMED AND I WASN'T SURE WHETHER I HAD GOTTEN RID OF
	THEM SO I QUICKLY GOT OUT OF THE CHUTE AND WHEN I TOOK A LOOK
	AT THE CHUTE, I SAW THAT THE RISERS WERE STILL CONNECTED,
	HELD THROUGH THAT ANTENNA CORD, YOU KNOW WHAT I MEAN?
25XTA	
	IT HAD COLLAPSED THEN, THIS WOULD OF BEEN ALRIGHT BECAUSE
	THIS IS JUST AN ANTENNA AND IT WOULD HAVE PULLED ON OUT HAD
	IT HAD ANY WIND IN THE CANOPY
25X1A	
	I KNOW IT WOULD HAVE. IT'S AWFUL TIGHT.
25X1A	· 
	IT'S A SLIP PLUG WITH A SLIP RING. THANK YOU 25X1A
	QUESTION: -
	YOU HAD OXYGEN ALL THE WAY TO THE GROUND?
- /	

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

	WHETHER YOU LOOKED OR YOU JUST FELT AND FOUND THEM THERE.
25X1A	NO I LOOKED.
25X1A	YOU LOOKED?
25X1A	I HAD TO FEEL FOR THE A I HAD TO FEEL FOR THAT D-RING. I COULDN'T SEE. I WAS, YOU KNOW, WHEN YOU COME DOWN LIKE THAT
	YOU - YOU CAN'T SEE - YOU HAVE TO FEEL FOR THINGS.
25X1A	THAT'S FINE I WILL GET SOME MORE DETAILS AFTER YOU HAVE RESTED AND ALL THE EQUIPMENT IS BACK IN AND WE CAN LOOK IT OVER AS WE NO (TAPE DISTORTED)- ANYTHING DAMAGING FROM THE AIRPLANE OR FROM ANY OF THE EQUIPMENT AT ALL. EVERYTHING SEEMS TO BE JUST PERFECT.
25X1A	THERE IS EVIDENCE HOWEVER THAT HIS HEAD WAS BANGED AROUND A BIT IN THE COCKPIT BEFORE HE BAILED OUT BECAUSE HE HAS A BIG
	GASH IN RIGHT SIDE OF HELMET.

THE STREET

25X1A	
	SCRATCHED AREA. ITS NOT CRACKED HOWEVER. THE HELMET HELPED.
25X1A	
	NO ITS IN VERY GOOD CONDITION.
25X1A	
	CAN ANY GENTLEMEN FROM LOCKHEED THINK OF ANYTHING ELSE
	WHILE WE ARE HEARING THIS?
25X1A	
	NO. THE EJECTION SOUNDS GOOD TO ME.
25X1A	
	ANYBODY HAVE ANYTHING TO ADD THEN, THAT THEY THINK WOULD
	BE OF ANY HELP? OK THEN THIS WILL CONCLUDE THEN THE DEBRIEFING
25X1A	FOR

STATEMENTS FROM CREW OF KC 135

25XTA

25X1A

25X1A

25X1A

I'M AIR CORPS AIRCRAFT COM- 25X1A
MANDER ON KC 135, THAT OBSERVED A DISINTEGRATION OF
A U2 TYPE AIRCRAFT IN FLIGHT. THIS INCIDENT OCCURED ON 25 FEB
AT APPROXIMATELY 1818 ZULU, AT FLIGHT LEVEL 350, THIS WAS
AFTER APPROXIMATELY 30 MINUTES OF PRACTICE AIR REFUELING.
THE AIR REFUELING PORTION OF IT WAS VERY GOOD, NO TURBULENCE.
THERE WAS NO INDICATION THAT THE PILOT IN THE U2 WAS HAVING ANY
PROBLEM WITH THE AIRCRAFT. HE CALLED A PRACTICE BREAKAWAY
WHICH WAS EXECUTED SUCCESSIVELY. I HAD EXCELERATED TO
APPROXIMATELY 220 KNOTS INDICATED AIR SPEED, AND HE PULLED
BACK UP AND WAS FLYING FORMATION. MY COPILOT AND NAV WERE
BOTH LOOKING OUT THE RIGHT WINDOW. HE WAS FLYING ON MY RIGHT
WING AT APPROXIMATELY 200 FEET OFF THE RIGHT WING. HE FLEW
THIS POSITION FOR APPROXIMATELY 1 MINUTE, OR TWO MINUTES, AND
THEN HE MADE A PULL UP AT WHICH TIME HE WENT OUT OF MY SIGHT.
SHORTLY THEREAFTER THE COPILOT SAYS TO ME THAT HIS WING IS 25X1A
COMING OFF, AND I ASKED WHAT, AND HE SAID "HIS WING IS COMING OFF  25X17A  25X17A
HE'S DISINTEGRATING". AND I IMMEDIATELY CALLED CONTROL
AND NOTIFIED THEM. I CALLED A CHASE AIRCRAFT, A T-BIRD,
AND NOTIFIED HIM. HE CAME BACK IN AND FLEW COVER. HE WENT
ON DOWN. I WENT DOWN TO 14,000 AND THEN WHEN HE RAN OUT OF

FUEL AND WAS GETTING LOW ON FUEL. WHEN HE LEFT I WENT ON DOWN TO ABOUT 8,500 FEET AND WE WERE ABLE TO OBSERVE THE DEBRIS FOLLOWING THE PILOT WAS IN DEBRIS - DEPLOYMENT OF THE CHUTE, AND WERE ABLE TO TALK TO THE PILOT ON THE GROUND AFTER THE OTHER AIRCRAFT LEFT AND WE HOVERED TO MAINTAIN 25X1A COVER UNTIL ANOTHER CHASE AIRCRAFT OF RETURNED AND THEN TWO RECOVERY HELICOPTERS CAME IN. WE WERE ABLE TO CONTACT THE PILOT ALTHOUGH WE WERE UNABLE TO READ WHAT HE WAS SAYING DUE TO THE LOCATOR BEACON BLOCKING HIM OUT. IT WAS JAMMING HIS RADIO VOICE TRANSMISSION. AND I FINALLY GOT HIM TO TURN OFF HIS LOCATOR BEACON AND HE TALKED TO US AND TOLD US HE WAS ALRIGHT AND EVERYTHING AND THEN AS SOON AS THEY SAID - THE CHOPPER SAID THEY HAD HIM AND EVERYTHING WAS - THEY WERE PICKING THE PILOT UP, WE WERE RELEASED BY OUR TO GO HOME. QUESTION: -DID THE COPILOT SAY WHICH WING HAD COME OFF? I THINK AT THE TIME HE SAID THE LEFT WING CAME OFF AND I ALSO THINK THAT MY NAV SAID IT'S THE LEFT WING.

25X1A

25X1A

25X1A

I SEE.

NOR!

25X1A	
	AND THEY INDICATED TO ME THAT IT BROKE OFF RIGHT AT THE
	AIRCRAFT.
	QUESTION: -
	RIGHT AT THE ROOT?
25X1A	
	RIGHT. NOW HE WAS NOT SURE AT A LATER TIME BECAUSE OF THE
	SPINNING OF THE AIRCRAFT BUT HE THOUGHT THAT IT WAS THE LEFT
	WING THAT COME OFF.
25X1A	
	AND THAT WAS THE VERY FIRST STATEMENT OF YOUR COPILOT, WAS IT?
25X1A	
	RIGHT.
25X1A	_
25X1A	THAT THE WING HAD COME OFF?
	· · · · · · · · · · · · · · · · · · ·
	RIGHT.
25X1A	
	I SEE.

QU]	EST	101	√: -
-----	-----	-----	------

AS FAR AS YOU KNOW THERE IS NOTHING UNUSUAL ABOUT THE RE-FUELING?

25X1A

NO SIR, THE REFUELING WAS EXCELLENT. IN FACT, THE RECLIVER PILOT MADE THREE OR FOUR OF THE CONTACTS HIMSELF. I MEAN HE ACTUALLY - ALL OUR BOOMER DID WAS LINE HIM UP AND LET HIM FLY RIGHT IN TO THE CONTACT POSITION. VERY SMOOTH, NO SIGNIFICANT BUMP. I MEAN NOT EVEN AS MUCH BUMPING AS WHEN THE BOOM OPERATOR. AFTER THIS THE LIGHT CAME ON TO INDICATE CONTACT MADE.

25X1A

NO FUELING HOWEVER?

25X1A |

SIR?

25X1A

NO FUELING - JUST -

PUCKETT: -

THERE WAS NO FUEL. AT ONE CONTACT THE BOOM OPERATOR TOLD
HIM THAT HE HAD A SPRAY FROM AROUND THE RECEPTACLE, AND
THEN IT QUIT. AND OUR BOOM HAD NO FUEL IN IT SO IF IT WAS SPRAY.

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

W WIND

	IT WAS DUE TO THE POSITION THE BOOM WAS IN AND THE FACT THAT
	HE WAS PRESSURIZED AGAINST IT, IS THE ONLY WAY THAT
25X1A	THAT WAS ON ONE OCCASION, WAS IT?
25X1A	THAT WAS ON ONE OCCASION, WAS IT?
	THAT WAS ON ONE OCCASION AND THAT WAS EARLY IN THE CONTACTS.
25X1A	
	YOU DID NOT SEE THE ACTUAL INCIDENT - YOU SAW THIS WHEN YOU
	CAME DOWN 8,000 FEET, YOU SAW WHAT WAS FALLING.
25X1A	
	NO I NEVER ACTUALLY SAW ANY OF THE DISINTIGRATION OR THE PARTS
25X1A	FALLING.
	OK.
25X1A	
	MY COPILOT DID SAY, AFTER THE WING, HE SAID HIS LEFT WING JUST
	CAME OFF AND THEN HE SAID THE ENGINE JUST FELL OUT. HE SAW THE
	ENGINE. HE SAW IT IN THREE DISTINCT PARTS THAT WERE TOGETHER.
	THE WING CAME OFF, A ROLL, A DISINTIGRATION OF WHICH THE ENGINE
	CAME OUT IN ONE PART AND THE NOSE SECTION WAS STILL INTACT IN

ANOTHER PART. NOW THE BOOM OPERATOR, HIS FIRST STATEMENT

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

RIGHT AFTER THAT WAS. "WELL I SEE HIM, I SEE THE PILOT". AND HE WAS IN - ACCORDING TO WHAT THE BOOM OPERATOR SAID ON THE INTERPHONE - HE WAS IN THIS DEBRIS, THE PARTS OF THE AIRCRAFT FOLLOWING. CAPTAIN, WE UNDERSTAND THAT THERE WAS VERY SMOOTH AIR DURING, THROUGHOUT THE OPERATION. SHOULD WE BELIEVE THAT THIS IS THE CASE AFTER THE BREAK AND ALSO DURING THE TIME THAT THE AIRPLANE WAS FLYING ON YOUR WING? YES SIR, EXTREMELY SMOOTH AIR, IT WAS SOME OF THE BEST THAT I HAVE FLOWN REFUELING AGAINST THE UZ IN. WHAT WAS YOUR MAXIMUM SPEED DURING REFUELING? IT WAS 200 KNOTS AND I WOULD SAY THAT IT DIDN'T VARY MORE THAN 2 KNOTS EITHER SIDE.

25X1A

25X1A

25X1A

25X1A

25X1A

I SEE. FINE. DID YOU START TO - WHEN YOUR COPILOT GAVE YOU AN INDICATION THAT THE AIRCRAFT HAD BROKEN UP, DID YOU START TO ORBIT?

25X1A

25X1A

YES SIR, AND THAT'S WHEN THE BOOM OPERATOR WAS - HE SAW THE DEBRIS COMING BY AND IT FALLING, AND I MADE A TURN TO STAY AS CLOSE TO THE POINT AS I COULD AND HE LOST IT. AND THEN HE DIDN'T ACTUALLY, I DON'T BELIEVE HE ACTUALLY SAW THE CHUTE DEPLOY. AND HE SAID HE SAW THE PILOT AND WHEN I MADE THE FIRST CALL TO I SAID THAT WE HAD A CHUTE AND THEN ABOUT 15 OR 20 SECONDS LATER I SAYS NO WE DON'T HAVE A CHUTE YET. WE HAD THE PILOT. AND THEN APPROXIMATELY, I GUESS, HE MUST HAVE FLAILED FOR A MINUTE OR SO BEFORE WE SAW THE CHUTE. AND THE CHASE PLANE DID SEE THE CHUTE DEPLOYMENT, I BELIEVE THO. THE INITIAL DEPLOYMENT OF THE CHUTE. HE MUST HAVE WENT TO AROUND 14,000 BEFORE HE DEPLOYED THE CHUTE. WHICH WOULD BE THE NORMAL - I DON'T KNOW WHAT - I WOULD GUESS THAT THAT WOULD BE WHAT IT - THAT'S WHAT OUR CHUTES ARE SET FOR, SO I DON'T KNOW, MAYBE A HIGHER TERRAIN HERE. YOU MAY SET THEM HIGHER, BUT --

BACKGROUND COMMENT: -

I THINK YOU'D PULL IT.

25X1A

WELL I DON'T KNOW BUT I MEAN I'M JUST - HE FELL FOR SOME TIME BEFORE THE CHUTE WAS DEPLOYED.

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

14.

QUESTION: -

CAN WE FIND OUT A LITTLE BIT MORE - THIS SPELL PECIME WE'RE
TALKING ABOUT? WHEN YOU SAID YOU ACCELERATED TO ABOUT 220,
HAD THE PILOT ALREADY COME UP ON YOUR WING AT THE TIME YOU
WERE GOING THROUGH SAY, 210?

25X1A

25X1A

NO SIR. HE CALLED A BREAKAWAY, I ACCELERATED, WELL FIRST OF ALL THE BOOM OPERATOR CALLED, "YOU'RE CLEAR TO CLIMB". WHICH I CAN'T DO. I GOT TO DROP THE NOSE OVER AND START AN ACCELERATION IN THIS AIRCRAFT. I CAN PUT ALL THE POWER THERE AND I CANNOT ACCELERATE WITHOUT DESCENDING. HE MADE - ACTUALLY THE BOOM OPERATOR MADE A WRONG CALL. HE SAYS -SHOULD HAVE SAID, "YOU ARE CLEAR TO DESCEND" IN THIS SPECIFIC AIRCRAFT, BUT IN ALL OTHER AIRCRAFT HIS CALL IS "YOUR CLEAR TO CLIMB" ON THE BREAKAWAY. BUT THIS IS ALL ON THE INTERCOM. THIS WOULD NOT AFFECT THIS AT ALL AND I TOLD HIM, I SAID, "I CAN'T CLIMB I GOT TO DESCEND AM I CLEAR"? AND HE SAID "YES" SO I DESCENDED AND THEN I BELIEVE THAT CALLED AND TOLI25X1A HE'D BE ON THE GROUND IN 10 MINUTES, TO CHANGE PILOTS. I'M NOT SURE WHETHER HE SAID IT BEFORE OR AFTER THE BREAKAWAY BUT HE HAD CALLED THEM AND TOLD THEM HE'D BE ON THE GROUND IN 10 MINUTES AND THE OTHER GUY SAYS "I'M GOING IN TOO" AND HE

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

DID A ROLL-OVER ON THE LEFT, THE T-BIRD PILOT DID, AND THERE

## Approved For Release 2002/06/13 CIA-RDP74B00447R000100010065-0

Page 36

WAS SOME COMMENT MADE TO HIM ABOUT, WELL I THOUGHT HE
WOULD MAKE MY COPILOT SICK. HE IS JUST OUT OF PILOT TRAINING
ABOUT 9 MONTHS, AND HE SAYS I'M MAKING MYSELF SICK TOO AND
THEN DEAK FLEW UP ON THE RIGHT WING. HE WAS FLYING FORMATION
AND I WOULD SAY THAT IT-SOMEWHERE IN THE VICINITY OF 220. I
KNOW THAT I LOOKED AT MY AIRSPEED INDICATOR AND IT WAS 220
AT ABOUT THE TIME THAT HE PULLED UP.

25X1A

25X1A

AND HE WAS KEEPING WITH YOU AT THAT TIME?

25X1A

YES, SIR. HE WAS FLYING FORMATION WITH ME.

DID YOU HEAR ANY FURTHER TRANSMISSIONS AFTER THE TRANSMISSION TO THE EFFECT THAT HE WOULD BE ON THE GROUND IN 10 MINUTES?

25X1A

OH, I'M SURE WE SAID SOMETHING. OH HE DID SAY, SOMEBODY SAYS
HE FLEW AN HONEST 200 - WAS DURING THE REFUELING, WHICH SORT
OF SUPRISED ME BECAUSE 200's JUST WHAT I'M SUPPOSED TO FLY.
I WAS JUST THINKING THAT MAYBE SOMEBODY ELSE THAT HE HAD BEEN
WORKING WITH HADN'T BEEN FLYING 200 BUT HE DID SAY "YOU FLEW
AN HONEST 200". AND WE ALSO - THE T-BIRD DID, AFTER, OH BEFORE

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

HIS BREAKAWAY, THE T-BIRD HAD BEEN IN AND LOOKED AT THE LIGHTS, I BELIEVE THE PILOT THAT WAS IN THE T-BIRD WAS TO FLY THE NEXT REFUELING. WE WERE SCHEDULED FOR TWO CONTROL TIME. AND HE CAME IN TO SEE - HE HAD NEVER SEEN THE ACTUAL BOOM LIGHTS AND SO FORTH AND HE CAME IN FIRST AND HE DIDN'T SEE THE GREEN LIGHTS WHICH HE WOULD NOT SEE UNTIL WE WENT TO A CONTACT MATE SO I HAD THE BOOM OPERATOR TO MANUALLY MAKE THE CONTACT MADE WHICH WE CAN DO IN OUR SYSTEM AND THEN WHEN HE CAME IN HE FLEW THE BOOM AROUND TO SHOW HIM HOW THE LIGHTS GO UP AND DOWN THE AIRCRAFT AND SO FORTH.

QUESTION: IS THIS BEFORE DEAK ---

HE WAS STILL WITH US. WE WERE ALL THREE TOGETHEN WHEN ---

QUESTION: -

25X1A

25X1A

THIS WAS BEFORE OR AFTER DEAK HAD DONE HIS WORK?

OH, HAD BEEN AT WORK QUITE AHWILF.HE HAD BEEN AT WORK

FOR PROBABLY 20 OR 25 MINUTES. I DON'T REMEMBER IF CAMESX1A

IN AGAIN AFTER HE LOOKED AT THE LIGHTS OR NOT BUT I KNOW THAT

HE DID COME IN AGAIN BECAUSE THE BREAKAWAY WAS THE FINAL TIME,

THAT'S THE LAST THING THAT WE HAD WAS THE BREAKAWAY AS FAR AS THE REQUIREMENTS FOR HIM WERE CONCERNED.

QUESTION: -

WELL AFTER YOU FLEW FORMATION THERE, MOMENTARILY, AND YOU WERE DOING ABOUT 220, WHAT KIND OF A PULL UP DID HE DO?
YOU SAID - WOULD YOU DESCRIBE IT AS SHARP, AND WHAT KIND OF AN ANGLE WOULD IT BE?

25X1A

NOT SEEING THE WHOLE PULLUP, MY COPILOT DESCRIBED IT AS A TAKEOFF, A NORMAL TAKEOFF CLIMB. IN OTHER WORDS, BEING A 135 PILOT, I WOULD SAY IT WAS A FAIRLY ABRUPT PULLUP, IN OTHER WORDS, THIS IS A PRETTY GOOD CLIMB ANGLE HE MUST NOT HAVE GOTTEN MORE THAN 500 OR A 1000 FEET EVEN WITH THE CAPABILITY HE'S GOT TO CLIMB BEFORE HE STARTED TO BREAKING UP BECAUSE IT WAS ALMOST INSTANTANEOUS. I WAS WATCHING HIM WHEN HE PULLED UP, AND ALMOST IMMEDIATELY, I WOULD SAY WITHIN 5 SECONDS OR SO THE COPILOT SAID THE WING IS COMING OFF.

QUESTION: -

YOU SAW HIM TRANSITION FROM LEVEL FLIGHT?

25X1A

YES SIR.

# TOP SECRET Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0 Page 39

	QUESTION: -
	WAS THAT ABRUPT?
25X1A	
	I WOULDN'T SAY THAT IT WAS - I MEAN - NOT BEING IN THE AIRPLANE
	I COULDN'T SAY HOW MANY G FORCES HE PULLED, I MEAN, EVERY-
	THING THE BIRD DOES SEEMS ABRUPT TO ME BECAUSE I FLY IN A
	DIFFERENT ATMOSPHERE AND I WOULD BE AFRAID TO HAZZARD A
	GUESS AND I WOULDN'T WANT TO GUESS SINCE YOU'RE TRYING TO
	FIND OUT.
	QUESTION: -
25X1A	SAID, I WOULDN'T WANTA - AS HE WINGED OVER HE HAD 210.
	HE REMEMBERED THAT. WHAT'S THE G FORCE AT 220 AT 35,000
	IN THIS BIRD? THAT'S WELL WITHIN THE REGIME.
25X1A	
	OH YES INDEED -
25X1A	
	WITH GUST CONTROL ON:
25X1A	-
	THERE WAS ONE THING WHEN HE WAS FLYING FORMATION. I NEVER
	SAID IT BUT I THOUGHT IT, THAT THE WINGS LOOKED LIKE THEY
	WERE FLAPPING HE LOOKED MORE LIKE - WE CALL IT THE BLACK

BIRD ALL THE TIME. AND THAT'S TRUTHFULLY WHAT I THOUGHT IN MY MIND - HE LOOKS LIKE HE'S OUT THERE FLAPPING BECAUSE THE WINGS WERE FLEXING - HOW MUCH - A COUPLE OF FEET OF FLEXING. IT WAS DEFINITELY A FLEX OUT ON THE OUTER PORTION OF THE WING. I'VE NEVER REALLY GOT A GOOD VIEW OF THE AIRCRAFT OTHER THAN WHEN I WAS INITIALLY CHECKING OUT.

NEXT 14 FEET OF TAPE DISTORTED.

#### 25X1A

NO SIR HE WAS IN FRONT OF MY WING. I MEAN, BUT WHEN I SAY
"OFF MY WING" I MEAN OUT, HE'S PROBABLY MAYBE 300 FEET OUT
TOTAL DISTANCE FROM ME. BUT HE WAS ACTUALLY UP, WE COULD
ACTUALLY LOOK FROM COCKPIT TO COCKPIT. IT WAS LIKE YOU AND
I ARE - HE WAS IN FRONT OF ME AND I DON'T THINK AT 220 I'D BE
PUSHING VERY MUCH AIR OUT - (DISTORTED.)

NEXT 4 FEET OF TAPE DISTORTED.

#### 25X1A

FROM THE TIME HE BROKE AWAY TILL HE WAS BACK IN POSITION - 2 TO 3 MINUTES.

#### 25X1A

BEFORE HE STARTED TO CLIMB?

		rage
25X1A		
	RIGHT. AND THEN HE CAME UP AND MAYBE FLEW A MINUTE OF	R SO
	AND STARTED TO CLIMB.	
25X1A		
	POSSIBLY 3 TO 4 MINUTES THEN, FROM THE TIME HE BROKE AW	A
	AND THE TIME HE STARTED TO CLIMB?	
25X1A		
	RIGHT. I MEAN THIS IS JUST A GUESS ON MY PART. I DON'T	
25X1A	THREE FEET OF TAPE DISTORTED.	
	HE DID HAVE BOARDS OUT WHEN HE WAS FLYING BESIDE ME. I	DON'T
	KNOW IF - HE WAS NOT CLEAN AT THE TIME HE WAS FLYING FOR	RMA-
	TION. I COULD SEE THAT THE SPEED BOARDS WERE OUT.	
	ONE FOOT OF TAPE DISTORTED.	
	QUESTION: -	
	DOES THAT AGRIVATE THIS WING FLEXING ANY?	
25X1A		
	NO, BUT YOU ONLY NEED VERY, VERY SLIGHT MINOR TURBULEN	CE TO
	DEFLECT THAT WING CONSIDERABLY AND IT WAS WAY OUT AT T	
	ONE FOOT OF TAPE DISTORTED.	

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

25X1A	
	THAT'S THE WAY THEY WERE DOING.
25X1A	
	ONLY MINOR TURBULENCE WOULD CAUSE THAT.
	FIVE FEET OF TAPE DISTORTED.
	QUESTION: -
	WAS THAT PYLON STILL ON THE LEFT WING FOR THE POD DEAL
25X1A	
	NO SIR. IT HAD THE SLIPPER TANKS.
$\overline{}$	TWO FEET OF TAPE DISTORTED.
25X1A	
	ON THIS CLIMB OUT, HE MADE A CLIMBING TURN, DID HE, OR COULD
	YOU TELL?
25X1A	
	NO SIR, WELL, I DON'T - I HAD A VERY LIMITED VIEW AT THE TIME.
	ALL I SAW WAS THAT HE WENT UP.
• 25X1A	
	AS HE WENT UP DID YOU NOTICE THE BOARDS WERE STILL OUT?

25×1 A		٠

NOT WHEN HE WENT UP. WHEN HE WAS FLYING FORMATION I DO REMEMBER THE ONES ON THE SIDE, I GUESS THEY'RE SPEED BRAKES, THAT'S WHAT I CALL THEM ANYWAY - WERE OUT WHEN HE WAS FLYING FORMATION.

ONE AND ONE-HALF FEET OF TAPE DISTORTED.

#### COMMENT: -

THEY ARE HYDRAULICALLY CONTROLLED FROM ONE SOLENOID VALVE. I THINK FOR IT TO HAPPEN WHERE ONE WOULD DO THIS, THAT YOU COULD HAVE - YOU HAVE A RESTRICTOR IN THESE LINES - IF THAT BECAME OBSTRUCTED ON ONE SIDE YOU COULD HAVE ONE CLOSED -(DISTORTED)

ONE FOOT OF TAPE DISTORTED.

#### 25X1A

YOU MIGHT GET A SLIGHT YAW.

#### 25X1A

YES PROBABLY WOULDN'T MAKE A TREMENDOUS DIFFERENCE.

IT WOULDN'T BE ENOUGH THOUGH TO PUT ANY TENSION OR TORQUE ON THE WING (DISTORTED) CAUSE IT TO COME OFF.

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

Thomas areas

	TWO FEET OF TAPE DISTORTED.
5X1A	WELL, THE FIRST THING HE FELT WAS THE SHUDDER - (DISTORTED)
	OUESTION: - YOU SAID THAT THEY WERE OUT WHEN HE WAS FLYING FORMATION
	AND I'M NOT SURE WHETHER YOU SAID THEY WERE IN WHEN HE PULLED UP.
5X1A	I DON'T KNOW.
5 <del>%1</del> ′A	YOU DON'T KNOW.
5Χ1Δ	

WHEN HE PULLED UP WHETHER THEY WERE IN. NOW THEN, IF YOU'RE INTERESTED ON HEARING TALK THAT WENT ON IN THE COCKPIT ABOUT WHAT HAPPENED OTHER THAN THAT, OR OPINIONS AND SO FORTH.

I'LL BE WILLING TO TALK ABOUT THAT. YOU CAN ASK ME QUESTIONS ABOUT THAT AND I CAN TELL YOU SOMETHING ELSE. BUT, I MEAN, THE THINGS THAT I ACTUALLY SAW, I'M TRYING TO PUT ON THE TAPE FIRST. I MEAN, THIS IS WHAT I WANT. AND THEN WHAT THE OTHER

GUYS SAID TO ME AND SPECIFICS, IF YOU WOULD LIKE TO, MAYBE WHAT THEY SAID TO ME THEY MAY FORGET. AND YOU MAY ASK THEM THESE QUESTIONS LATER. BUT AS FAR AS THE SPECIFICS, I HAVE MY SPECIFICS DOWN AND I'M TRYING TO KEEP WHAT I SAW SEPARATED FROM WHAT THE OTHER GUYS TOLD ME. AND THIS IS THE WAY I THINK YOU WANT IT.

25X1A

YES. WE WILL HAVE THEM IN AND IF THEY'RE UNSURE ABOUT
MAYBE SOMETHING THAT THEY SAID AT THE TIME, THEN WE MIGHT

REFER BACK TO YOU FOR (DISTORTED)

COMMENT: -

I THINK THAT WOULD BE A GOOD PROCEDURE. TALK TO THEM FIRST,
THEN WE CAN GET THEM ALL TOGETHER.

25X1A

YES.

25X1A

THE PURPOSE OF THIS IS TO TRY TO FIND OUT WHAT MADE THAT WING COME OFF.

25X1A	
	I ORBITED TO THE RIGHT AND HE WATCHED AND THE BOOM - OR
	ACTUALLY - WELL I'M GOING TO HAVE TO GET?? - THE WING CAME
	OFF HE'S SAIS THE WING CAME OFF. HE'S IN A SPIN OR ROLL. IN OTHER
	WORDS IT WAS A SPIN HE WAS CALLING IT A SPIN BUT ACTUALLY I
	WOULD THING THAT IT'S A ROLL. AND THEN ALMOST IMMEDIATELY
	THE BOOM OPERATOR SAYS "I SEE HIM - I SEE IT - I SEE THE PILOT
	HE'S RIGHT IN THE DEBRIS". AND SO I IMMEDIATELY STARTED TO TURN
	AND HE SAID "IF YOU DON'T TURN I CAN SEE HIM" AND I SAYS "I WOULD
	RATHER BE OVER THE SPOT" AND SO I STARTED TO TURN AND THAT
	PUT THE COPILOT OUT WHERE HE COULD SEE. WE GOT AT LEAST A GOOD
•	360 BEFORE WE SAW THE CHUTE DEPLOY, SO THAT'S APPROXIMATELY 4
	MINUTES. I DON'T KNOW. BEFORE WE SAW THE CHUTE I WOULD SAY.
	I WON'T SAY THAT IT DEPLOYED. IT WAS PROBABLY 4 MINUTES. WE
25X1A	IMMEDIATELY CALLED WITHIN 15 SECONDS FROM TIME
	IT HAPPENED SO IF YOU LOGGED IT IN YOU GOT A BETTER TIME THAN
	WE PROBABLY GOT.
05V4A	
25X1A	
	WHEN YOU WERE FLYING FORMATION YOU WERE AT ABOUT 35,000?
25X1A	
	YES SIR. I WOULD SAY THAT WE WERE BETWEEN 34.5 and 35.
	BECAUSE ONCE IT STARTED ACCELERATING I DIDN'T CONTINUE ON. WE

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

+ 17, 753,38, 18

	WERE TOLD TO STAY NORTH OF 40 MILES NORTH OF PALMDALE AND
	WE WERE APPROACHING WITHIN A FEW MILES OF THAT. AND WE WERE
25X1A	GOING SOUTH AND GOT JUST ABOUT TO THAT POINT.
	ANYBODY THINK OF ANY FURTHER PERTINENT QUESTIONS?
25X1A	
	I HAD A MAP I JUST WONDERED HOW CLOS: OUR POINT WAS TO
	WHERE WE ACTUALLY SAID IT WAS. SOMEWHERE, RIGHT ALONG THERE
	IS ABOUT WHERE WE THOUGHT THE PILOT WAS, AND WE GUESSED THAT
	THE AIRCRAFT WAS PROBABLY FARTHER TO THE WEST. DOES THAT
<u> </u>	PRETTY MUCH CHECK? HAVE YOU GOT A POINT ON WHERE THEY
	PICKED HIM UP?
25X1A	THAT'S ALMOST IDENTICAL, ROUGHLY RIGHT THERE.
25X1A	WHERE'S THE POINT AT WHICH THE PULL-UP WAS STARTED?
25X1A	
	I WOULD GUESS IT WAS PROBABLY - LETS SEE NOW, WE CAME - HE
	WAS ON OUR -
	EIGHT FEET OF TAPE - NO SOUND.

COPILOT ON THE RC 135 TANKER WHICH WAS

COPILOT

25X1A

AT TIME OF THE ACCIDENT. THE EVENTS WORKING WITH WERE THAT25X1A WHICH TOOK PLACE RIGHT AFTER THE PRACTICE WITH HE CAME UP ON OUR RIGHT WING AND FLEW FORMATION ABOUT A COUPLE HUNDRED FEET OFF OUR WING FOR ABOUT A MINUTE OR SO AND THEN HE STARTED A PULL UP - WHICH - STARTED A PULL-UP, A SHARP PULL UP, IT LOOKED LIKE A NORMAL TAKEOFF PULL-UP TO ME. THEN STARTED A RIGHT BANK. TO THIS POINT EVERYTHING LOOKED NORMAL. THE FIRST THING I NOTICED WAS SOME FUEL SPRAY. IT WASN'T CONTRAIL. I'M SURE IT WAS FUEL OR SOMETHING, WHICH LOOKED LIKE IT WAS COMING OUT OF THE BOTTOM OF THE PLANE NEAR THE LEFT WING ROOT. I THOUGHT THIS WAS NORMAL. THE NEXT THING I NOTICED WAS THE WING BUCKLED AT THE ROOT. I THINK IT WAS THE LEFT WING. I COULDN'T BE POSITIVE. I THINK IT WAS THE LEFT WING. THE NEXT THING - AT THIS TIME EVENTS STARTED TAKING PLACE VERY RAPIDLY. THE NEXT THING, THE PLANE STARTED ROLLING AND ROLLED MODERATELY FAST AND IT WAS AT THIS POINT THAT EVERYTHING STARTED COMING APART. THE AIRPLANE ITSELF WAS PRETTY MUCH INTACT UNTIL AFTER THE WING LEFT AND FELL BEHIND THE AIRPLANE. THEN IT STARTED ROLLING AND THEN EVERYTHING

STARTED DISCENTEGRATING. I SAW TWO MAIN PARTS. ONE WAS THE

ENGINE. I DISTINCTLY REMEMBER THE ENGINE IT LOOKED LIKE IT WAS GOING TO FALL RIGHT ON US BUT GRADUALLY IT SLOWED DOWN AND FELL BEHIND US. AND THEN THERE WAS A FAIRLY LARGE PIECE OF NOSE SECTION WHICH WAS INTACT BUT THOSE WERE ONLY TWO MAIN PIECES I SAW. THE NEXT THING I DID. I CALLED APPROACH CONTROL AND NOTIFIED THEM THAT THE AIRCRAFT WE HAD BEEN WORKING WITH HAD DISCENTEGRATED AND GAVE THEM OUR APPROXI-MATE POSITION ON THE PALMDALE VORTAK ABOUT 330 DEGREES, ABOUT 42 MILES. AND THEY HAD A SQUAWK 77 AND AT THIS TIME THE AND THE OTHER AIRCRAFT COMMANDER WAS ADVISING 25X1A CHASE. AND TO THE BEST OF MY KNOWLEDGE, AS I CAN REMEMBER, EVERYTHING TOOK PLACE, IT WAS JUST A MATTER OF SECONDS THAT ALL THIS TOOK PLACE IN. AND I BELIEVE THAT'S ALL I CAN REMEMBER ABOUT IT.

#### QUESTION: -

WHEN YOU SAY YOU SAW THE ENGINE, FIRST YOU SAY YOU SAW SOME-THING SPRAY OUT? THEN THE WING CAME OFF AT THE ROOT. THEN WHEN YOU NOTICED THE ENGINE, WHERE WAS THE TAIL? DO YOU REMEMBER? YOU NEVER DID SEE THE TAIL COME OFF BY ITSELF. WHEN THE ENGINE CAME OUT WAS IT BARE? 25X1A

IT WAS BARE. IT LOOKED JUST LIKE AN ENGINE SITTING ON TEST
STAND. YOU COULD SEE FITTINGS ON SIDE OF IT. THE LITTLE TUBES
AND KNOZZLES AND THINGS.

25X1A

25X1A

AND THE NOSE SECTION OF THE FUSELAGE WAS SEPARATE?

-

OF THE FRONT PART OF THE AIRCRAFT. THE NOSE IN PARTICULAR
WHICH WAS INTACT. I DON'I KNOW WHAT CONDITION IT WAS FOUND IN,
BUT RIGHT AFTER THIS, WHEN THE PLANE STARTED SPINNING THERE
WERE A LOT OF REAL SMALL PIECES ALL OVER. IT DIDN'T LOOK LIKE
IT WAS AN EXPLOSION BECAUSE NOTHING LIKE THIS HAPPENED UNTIL
AFTER THE WING LEFT. THE PLANE STARTED ROLLING, THEN IT
SEEMED TO COME APART. IT LOOKED LIKE FUEL COMING OUT OF THERE.
I WAS THINKING OF SIPHON A LITTLE FUEL ON TAKEOFF. UP TILL THIS
POINT I THOUGHT EVERYTHING WAS NORMAL. I DIDN'T THINK ANYTHING ODD ABOUT THAT. BUT THEN THE WING CAME OFF AND I KNEW
SOMETHING WAS WRONG.

25X1A

IT CAME FROM UNDERSIDE OF THE FUSELAGE?

	· • • • • • • • • • • • • • • • • • • •
25X1A	
25X1A	YES SIR.
	CAN YOU DEFINE IT AS BEING UNDERSIDE FUSELAGE OR UNDERSIDE
	OF WING?
25X1A	
	IT WAS UNDER THE FUSELAGE BUT VERY CLOSE TO WING ROOT WHERE
	THE WING JOINS. AND IT WAS THERE THAT THE WING BROKE RIGHT
	WHERE THIS FUEL WAS.
25X1A	
25X1A	YOU ARE REASONABLY SURE IT WAS LEFT WING THAT BROKE?
	THAT'S THE POINT. I'M NOT SURE. I'M NOT REASONABLY CERTAIN
	ON WHICH WING BECAUSE I THOUGHT IT ROLLED TO THE RIGHT. THEN
	SOMEONE SAID IF THE LEFT WING CAME OFF, IT WOULD HAVE ROLLED
	TO THE LEFT. I DON'T KNOW IF IT'S EXPLAINABLE OR NOT.
25X1A	
	OH YES, IT'S VERY DIFFICULT TO DETERMINE WHAT AN AIRPLANE
	WILL DO WHEN A MAJOR PORTION LIKE THAT COMES OFF. IT DOES
	SOME EXTRAORDINARY THINGS. WHAT IT WOULD DO, IS, AFTER THE
	EVENT ACTUALLY. IS NOT REALLY IMPORTANT TO IT. THE FIRST

IMPRESSION THAT YOU HAD OF WHICH WING CAME OFF. Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

25X1A	
	-
25X1A	MY FIRST IMPRESSION WAS THE LEFT WING.
٠	
	WOULD YOU HAVE A IMPRESSION WHETHER IT FAILED UPWARD OR
	DOWNWARD?
25X1A	
	UPWARD - AND I WILL TELL YOU SOMETHING ELSE WHICH, FOR THE
	FIRST TIME, I REALIZE NOW, WHY I THOUGHT IT WAS LEFT WING.
	BECAUSE HE HAD STARTED A PULL-UP, THEN STARTED A RIGHT BANK.
	I WOULDN'T HAVE BEEN ABLE TO SEE, I DON'T THINK, THE RIGHT
~	WING BREAK OFF AT THE ROOT AS WELL AS LEFT WING, BECAUSE IT
	WAS MORE EXPOSED. AS I RECALL NOW, HE HAD ALREADY STARTED
	A PULLUP, IT WASN'T SIMULTANEOUS. THEY WERE TWO DIFFERENT
25X1A	THINGS INVOLVED, PULL-UP THEN TURN.
	WHAT ANGLE OF BANK DO YOU THINK HE WAS?
25X1A	<u> </u>
	WHEN THE WING SEPARATED?
25X1A	
	YES.

I SAY ANYWHERE FROM 20 TO 30, 40 DEGREES. IT WASN'T A REAL
HAIRY TURN OR ANYTHING LIKE THAT. IT LOOKED LIKE A NORMAL
TAKEOFF. YOU KNOW HOW HE PULLS UP REAL STEEP AND STARTS
A TURN.

25X1A

AFTER WING CAME OFF DID YOU NOTICE A DIFFERENCE ANY METAL
COLOR? DID YOU ACTUALLY SEE THE RUPTURE AS A DIFFERENT COLORED FINISH AS OPPOSED TO THE BLUE?

25X1A

NO, I DON'T RECALL. I REMEMBER THE ENGINE AND IT WAS NOTHING BLACK ABOUT IT. IT LOOKED LIKE METAL TO ME. I WAS LOOKING AT THE THING THE WHOLE TIME AND I SAW EVERYTHING BUT I JUST CAN'T RECALL EVERYTHING.

25X1A

DID IT JUST LOOK LIKE AN ENGINE AS IT WOULD BE ON THE TEST STAND?

25X1A

RIGHT. IT WASN'T COVERED UP. NO PIECES ATTACHED TO IT OR ANYTHING.

25X1A	
	THERE WAS OTHER DEBRIS IN THE AIR AFTER THE WING FAILED PRIOR
	TO THE ENGINE COMING OUT.
25X1A	
	RIGHT. IT JUST SEEMED TO BE - THERE WAS SORT OF A - TOGETHER
	THERE - IT WAS MORE OR LESS SIMULTANEOUS. THE ENGINE AND
	EVERYTHING ELSE. THE WING CAME OFF BY ITSELF AND THEN EVERY
25X1A	THING ELSE SEEMED TO COME APART.
	<del></del>
	DID THE SHIP SEEM TO GO INTO A FLAT SPIN OF ANY SORT?
25X1A	
	NO, IT DIDN'T. IT DID
25X1A	
25X1A	IT WAS STRICTLY A ROLL, THEN?
	RIGHT. IT LOOKED LIKE A LEVEL SPIN OR A REAL FAST ROLL. A
	REAL SNAP ROLL OR SOMETHING. IT DEFINITELY WAS GOING AROUND
	LIKE THAT. NOW IF IT WAS GOING LEFT TO RIGHT, I'M NOT SURE
	AGAIN, BUT IT WAS GOING AROUND LIKE THAT AND THAT'S WHEN THE
	PIECES STARTED COMING OUT.

25X1A	
	WOULD YOU SAY THAT THE WING WAS ESSENTIALLY INTACT, OR WHEN
	YOU SAY WING, DO YOU MEAN BITS AND PIECES OF WING?
25X1A	
	NO, AS I RECALL IT, THE WING ITSELF, THE WHOLE THING CAME OFF.
	NOT JUST A PIECE OF IT. AND IT, FROM THE POINT OF THE ROOT OUT,
	IT FOLDED BACK UP, AND THEN ABOVE THE AIRPLANE AND THEN FELL
	BEHIND IT.
25X1A	` 
,	STILL INTACT?
25X1A	
	RIGHT.
25X1A	-
25X1A	AND YOU LOST SIGHT OF IT?
	THAT'S RIGHT. IT WAS JUST A MATTER OF SECONDS, THERE, AND IT
	SLOWED DOWN - ALL THE DEBRIS.
25X1A	· 1————————————————————————————————————
	THIS BEARING YOU TOOK OFF THIS TACAN, THE 330 RADIAL, 42 MILES
	FROM PALMDALE, HOW LONG AFTER THE INCIDENT WAS THAT?

25X1A	
	-
	IT WAS IMMEDIATELY. I LOOKED DOWN RIGHT THEN AND
25X1A	`
	RIGHT THEN AND THERE?
25X1A	
	RIGHT. AND CALLED APPROACH CONTROL.
	QUESTION: -
25X1A	WOULD YOU MIND ASKING TO PUT HIM AT THIS
	POSITION LEVEL AND SORT OF GRAPHICALLY GO THROUGH WITH THIS
	THING HERE, WHAT HE DID A PULL-UP, TURN, SO ON LIKE THAT AND
25X1A	KIND OF DESCRIBE IT. (U2 MODEL INTRODUCED.)
25X1A	THAT MIGHT WELL HELP, IF YOU'D DO THAT.
	I'LL SHOW THIS LIKE I AM SITTING IN THE COCKPIT, I'LL BE STANDING
	IN THE SEAT RIGHT HERE. NOW HE CAME OUT JUST A LITTLE BIT IN
	FRONT, HE WASN'T BEHIND OUR WING OR ANYTHING. HE WAS WELL OFF
	TO THE SIDE, JUST SLIGHTLY EVEN WITH US. I COULD LOOK OUT AND
	SEE HIM RIGHT THERE. HE FLEW OUT THERE ABOUT A MINUTE. THEN

JUST LIKE THEY ALWAYS ARE. TO ME THEY ARE VERY IMPRESSIVE.

STARTED TO PULL UP. HE PULLED UP LIKE THIS AND IT WAS BEAUTIFUL

THAT'S WHY THE NAVIGATOR HAPPENED TO BE WATCHING. HE STARTED A PULL UP LIKE THIS AND THEN HE STARTED LIKE THAT. NOW, AT THIS POINT I SAW FUEL SPARY COMING FROM RIGHT IN HERE. THEN IT LOOKED LIKE THE WING FROM RIGHT THERE WHERE IT ATTACHES THIS LITTLE MODEL, JUST WENT UP AND THEN STARTED FALLING BACK OVER THIS WAY BEHIND IT. THEN IT LOOKED TO ME LIKE IT WAS GOING LIKE THAT AND PIECES JUST STARTED FLYING.

25X1A	
25X1A	NO FIRE THAT YOU COULD SEE?
	NO FIRE AND IT DIDN'T SEEM TO BE A REAL EXPLOSIVE THING. IT
	JUST SEEMED TO BE A GRADUAL SEPARATION OF EVERYTHING.
	QUESTION: -
	WHEN HE WASAT THIS POSITION DID YOU NOTICE HIS DIVE BOARDS OR
25X1A	ANYTHING LIKE THAT?
	RIGHT. SURELY DID. THEY WERE OUT, RIGHT HERE, WHILE HE WAS

RIGHT. SURELY DID. THEY WERE OUT, RIGHT HERE, WHILE HE WAS WITH US AND I NOTICED AS HE STARTED HIS PULLUP THEY WENT IN.

JUST BEFORE HE STARTED HIS PULLUP THEY WENT IN.

QUESTION: -

DO YOU MIND IF I ASK THESE QUESTIONS,

25X1A

	•
25X1A	
	GO AHEAD, SIR.
	QUESTION: -
25X1A	WERE YOU NOTICING THE WING TIPS FLEXING AT THIS POSITION AT ALL?
	-
	WHEN HE PULLED IN TO US TO FLY FORMATION, JUST A VERY LITTLE.
	WHEN HE WAS OUT THERE WITH US THEY WERE VERY STABLE.
	QUESTION: -
	WAS THIS PULLUP AND WAS THIS A WING-OVER OR THIS BANK SIMILAR
~	TO OTHERS THAT YOU HAD SEEN?
25X1A	· · · · · · · · · · · · · · · · · · ·
	RIGHT. I'VE SEEN A COUPLE OF TAKEOFF'S IN OTHER PLACES THAT
	WE'VE BEEN. IT LOOKED TO ME LIKE A NORMAL PULLUP AT THE
	ALTITUDE. EVEN THE FUEL, UNTIL THE WING CAME OFF. EVERYTHING
	LOOKED NORMAL UNTIL I SAW THE WING SEPARATE. IT WASN'T UNTIL
25X1A	THAT POINT I REALIZED IT - SOMETHING WAS HAPPENING.
	WELL THERE'S QUITE A LOT OF DIFFERENCE BETWEEN TAKEOFF AND
	START OF MANEUVER LIKE THAT IN THE AIR BUT YOU ARE SAYING
25 <b>X1</b> A	

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

I'M NOT AWARE, YES --

THIS IS ON THE GROUND THAT YOU'RE COMPARING -
WELL I'M COMPARING TO -
-
YOU'RE COMPARING IT TO A 135 TAKEOFF ARE YOU?
WELL I'M COMPARING IT TO A TAKEOFF THAT I'VE SEEN FROM THESE
ON THE GROUND.
_
NORMAL U2 TYPE TAKEOFF?
QUESTION: -
YOU SAY YOU DON'T RECALL EVER HAVING SEEN THE TAIL DURING
THIS MANEUVER AND WHEN ALL THIS WAS TAKING PLACE.
· · · · · · · · · · · · · · · · · · ·
NO. THE TAIL DOESN'T START - I DON'T REMEMBER ANYTHING ABOUT
IT.
BEING AS HOW THE ENGINE IS BURIED IN THE FUSELAGE FORWARD OF
THE TAIL, WOULD YOU HAVE ANY OPINION AS TO HOW THE ENGINE MIGHT

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

25 <b>XT</b> A	HAVE GOTTEN OUT OF THE FUSELAGE? FUSELAGE BROKE UP OR?
DEV4.4	WELL YES, THE WHOLE THING BROKE UP, THE ONLY PIECE THAT I SAW THAT WOULD LOOK LIKE A PLANE WAS THE FRONT PART OF THE AIRCRAFT.
25X1A	COULD YOU SHOW US ON THE MODEL WHERE THE NOSE SECTION BROKE OFF?
25X1A	THIS AS OF JUST A BRIEF GLIMPSE HERE, SOMEWHERE RIGHT IN HERE -
	RIGHT UNDER THE HALF PART OF THIS CANOPY.
25X1A 25X1A	FUSELAGE APPEARED TO BREAK IN THAT AREA?
	THIS WAS THE PART THAT I SAW THAT WAS SORTA OF INTACT - JUST THAT LITTLE SECTION THERE RIGHT AHEAD OF-AND THESE TWO WERE THE LARGEST PIECES I SAW.
25X1A	AND THEN AFTER THE WING CAME OFF, YOU AT NO TIME SAW THE COCKPIT?

25X1A

THAT'S RIGHT, I DIDN'T SEE THE COCKPIT, I DIDN'T SEE THE PILOT.

I MIGHT HAVE SEEN THEM BUT I DON'T RECALL IT.

QUESTION: -

DO YOU RECALL DURING THE ROLL WHEN THE AIRPLANE ROLLED AS THE WING WAS COMING OFF, DO YOU RECALL SEEING THE OTHER WING AS A PART OF THE ROLL?

25X1A

NO SIR, I DON'T THINK SO THE WING CAME OFF LIKE THIS, HE WAS LIKE THIS, THE WING CAME OFF. IT STARTED ROLLING IT DIDN'T ROLL VERY MUCH AS AN AIRCRAFT BUT I REMEMBER SEEING A MOTION THERE. I THINK THIS LEFT WING, CORRECTION, THE RIGHT WING GAVE WAY RIGHT AFTER THAT BECAUSE I DON'T REMEMBER SEEING A ONE WINGED THING TURNING ON IT'S SIDE - IT MUST HAVE ALL JUST DISINTEGRATED RIGHT AFTER THE LEFT WING CAME OFF OR WHICH EVER WING CAME OFF.

QUESTION: -

THEN YOU DIDN'T SEE ANYTHING THAT LOOKED LIKE AN EXPLOSION?

25X1A

NO SIR, I HAVEN'T SEEN TOO MANY EXPLOSIONS OF AIRCRAFT OR OF

ANY OTHER THING BUT - EXCEPT IN MOVIES AND THINGS BUT TO ME IT

WASN'T ALL JUST LIKE THAT - IT WAS GRADUAL - THE WING GAVE WAY 
Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

	TURNING MOTION, BRIEF AS IT MAY HAVE BEEN, AND THEN IT JUST
	SORTA LIKE PIECES OF PAPER THAT JUST COME APART.
	QUESTION: -
25X1A	THERE WAS NO SMOKE?
	NO SIR, THERE WAS NO SMOKE, FIRE AND NO EXCELLERATED FLYING
	OBJECTS. IT JUST SORT OF CAME APART. I WOULD ASSOCIATE AN
	EXPLOSION WITH AN EXPLOSIVE FORCE AND PIECES FLYING OUT ALL
25X1A	OVER - I DIDN'T SEE ANYTHING OF THIS SO MY IMPRESSION OF IT WAS
	ROUGHLY, HOW MANY SECONDS DID YOU SEE IT FALL BEFORE THESE
	PIECES ALL DISAPPEARED FROM YOUR VIEW?
25X1A	
,	OH, THAT'S HARD TO SAY, I HAVEN'T EVEN THOUGHT. I WOULD SAY
	ANYWHERE FROM 10 TO 15 SECONDS.
25X1A	
25X1A	A FEW SECONDS YOU SAW IT FALL?
	<u> </u>
	YES.

25X1A	
	YOU SAID EARLIER ON THAT YOU WERE WONDERING WHETHER WE
	WANTED A OPINION OR NOT - WHAT IS THIS OPINION THAT YOU MIGHT
	HAVE?
25X1A	-
	BECAUSE OF WHAT - WHERE IT APPEARED TO BE JUST A GRADUAL
	THING - MY OPINION WAS THAT IT WAS NOT AN EXPLOSION. IT WAS
	JUST DUE TO THE WING COMING OFF - WHY THE WING CAME OFF I HAVE
	NO IDEA, BUT TO ME IF THE WING HAD STAYED ON I CAN'T SEE THE
	DISINTEGRATION PART. IT LOOKED TO ME, IF I WERE FLYING THE
	PLANE, I GUESS I WOULD JUST CALL IT STRUCTURAL FAILURE OF THE
	WING OR SOMETHING WITH NO SMOKE, FIRE, OR EXPLOSIVE FORCE.
25X1A	
	DID YOU HEAR ANYTHING ON THE RADIO AT ALL?
25X1A	
	NO SIR I DID NOT.
25X1A	
	THE PILOT HAS THIS IDEA. THE PILOT DID TRANSMIT?
25X1A	
	HE DID?

100

25X1A	1
	OR HE ATTEMPTED TO -
25X1A	
	HE ATTEMPTED TO.
25X1A	·
	HE REALIZED IT WAS VERY FUTILE. HE PRESSED THE BUTTON AND
	TRANSMITTED.I DON'T THINK HE'S SURE WHAT HE SAID HIMSELF BUT
	HE REALIZED IT WAS DEAD.HE LOOKED OUT AND SAW HIS RIGHT WING
	WAS GONE AND DECIDED, THEN DECIDED THEN AND THERE IT WAS
	TIME TO COME APART FROM THE AIRPLANE.
	QUESTION: -
	DO YOU REMEMBER WHAT SPEED YOU WERE AND WHEN - WHAT WERE
	YOU INDICATING? DID YOU NOTICE THAT AS HE STARTED TO PULL OUT -
25X1A	
	NO SIR. I DON'T REMEMBER. WE HAD JUST DONE A PRACTICE BREAKA-
	WAY AND HE HAD CALLED IT AND I DON'T REMEMBER WHAT SPEED WE
	WERE AT. I WAS LOOKING AT HIM. THE PILOT WAS FLYING. I WAS

LOOKING AT HIM TO WATCH THIS HAIRY PULLUP THAT THEY ALWAYS

DO AND I WASN'T OBSERVING THE AIRSPEED AND I COULDN'T RECALL

WHAT IT WAS.

## Same Shaked high

### Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0 Page 66

	QUESTION: -
	WHEN HE PULLED UP YOU DIDN'T NOTICE ANY PARTICULAR VIOLENT
	FLEXING OF THE WING AT THAT TIME?
25X1A	
	NO SIR. EVERYTHING WAS NORMAL - IT WAS JUST AS SMOOTH AND
	EVERYTHING WAS VERY SMOOTH.
25X1A	
	CAN YOU SAY WHETHER OR NOT THE BODY OF THE AIRPLANE AT ANY
	TIME ROLLED OVER ON ITS BACK OR FLIPPED OVER ON IT'S BACK.
25X1A	
	MY IMPRESSION OF THE ROLLING MOTION IS THIS - IT DIDN'T FLIP ON
	IT'S BACK JUST MOMENTARILY - THE WHOLE MASS, DEBRIS AND
•	EVERYTHING WAS TURNING AND THE PLANE STARTED TURNING AND IT
	WAS THEN THAT THE PIECES STARTING COMING OUT. IT WASN'T ANY
	KIND OF A MOTION LIKE THAT AND THEN STOP. IT WAS A CONTINUOUS -
25X1A	
25X1A	BUT IT KEPT ON ROLLING?
20/(1/(	,
	I DON'T KNOW IF YOU'VE SEEN ANYTHING LIKE THIS HAPPEN OR NOT -
ن پ	I GUESS FEW PEOPLE HAVE - BUT WHEN THE PIECES ALL STARTED
	COMING OUT - IT WAS NOTHING TO BOLL - THE BOLLING MOTION CRASED

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

25X1A	
ullet	
25X1A	JUST PIECES FLOATING AROUND?
25X1A	THAT RIGHT. THEN IT BECAME JUST PIECES FLOATING DOWN.
	YOU SAY YOU DIDN'T ACTUALLY SEE THE PILOT EJECT THEN?
25X1A	
	NO SIR, NEVER SAW THE PILOT. HE MIGHT HAVE BEEN IN MY VIEW
25X1A	BUT I DON'T RECALL SEEING HIM.
<b>—</b>	
	COULD YOU REDEFINE THE LARGE PIECES THAT YOU SAW THEN?
25X1A	
	I WOULD BE GLAD TO. THE ENGINE, I DON'T KNOW WHERE IT SITS
	IN THIS THING BUT POSSIBLY, PROBABLY BACK THERE IN THE MIDDLE
	OF THE SECTION BUT IT WAS A VERY LARGE ENGINE - TO ME ONE
	OF THE LARGEST ENGINES I'VE EVER SEEN AND IT WAS INTACT. AND
	I COULD SEE THE FITTINGS ON THE OUTSIDE - IT WASN'T COVERED
	UP BY AIRCRAFT SKIN OR THE OUTSIDE OF THE AIRPLANE. I COULD
25X1A	SEE THE FITTINGS AND NOZZLES.
	COULD YOU TELL IF IT HAD SOME LENGTH OF TAILPIPE HANGING ON IT

SHINY Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

NO SIR, IT WAS SORTA OF A YELLOWISH LOOKING - IT WASN'T SHINY -
BUT GOLDISH YELLOW, THAT COLOR. THEN THE OTHER SECTION
WAS IN THE NOSE - SOME PART UP HERE IN THE NOSE WHICH SEEMED
TO BE INTACT AND THESE WERE THE TWO LARGEST PIECES. EVERY-
THING ELSE WAS SO SMALL SO YOU CAN SEE HOW MUCH IT BROKE UP
IT WAS JUST ALMOST TOTAL.

25X1A

25X1A

THE WINGS MIGHT HAVE PASSED OUT OF YOUR VIEW AT THIS POINT?

\_\_\_\_\_-

I THINK THIS WING OR THE WING THAT BROKE OFF, WHICHEVER ONE IT WAS, I THINK IT BROKE OFF INTACT BUT THE OTHER WING I THINK JUST SORTA OF CRUMPLED UP. I SAW IT JUST LOOKED LIKE - YOU'VE SEEN PICTURES OF TORNADOES - HOUSES JUST SPLINTERS - THAT'S MY IMPRESSION OF IT. I THINK THE OTHER WING THAT STAYED ON THE AIRPLANE JUST SPLINTERED LIKE THAT.

25X1A

DID YOU NOTICE ANY PITCHING MOTION AT ALL, NOSE UP PITCHING

MOTION AT ALL AS THE WING CAME OFF OR AFTER IT CAME OFF?

25X1A

I DIDN'T NOTICE ANY MORE NOSE UP - I NOTICED A TURNING MOMENT.

25X1A	
~	
	BUT YOU DIDN'T NOTICE LITTLE OR NO
25X1A	_
25X1A	THAT'S RIGHT - LITTLE OR NO PITCH CHANGE - A ROLL.
	WELL AT SOME PERIOD WHEN HE STARTED HIS ROLLING PULL UP, A
	MATTER OF SECONDS AFTER HE STARTED THIS, YOU COULD SEE THE
25X1A	RIGHT-HAND WING AND LEFT-HAND WING STILL INTACT?
	RIGHT SURE COULD. AND MY IMPRESSION WAS - IT WAS LIKE THIS
	WHEN I WAS LOOKING AT IT AND THAT'S WHY I THINK IT WAS THIS WING
	CAUSE I HAD A BETTER VIEW OF IT AND I REMEMBER SEEING THE
	BREAK - I SAW THE INSTANT THE WING STARTED FOLDING BACK AND
25X1A	I DON'T THINK I COULD HAVE SEEN THAT HAD IT BEEN THE RIGHT WING.
	IT LOOKED TO YOU MORE LIKE THE FUEL WAS COMING FROM THIS AREA
	OTHER THAN THIS AREA?
25X1A	
	THAT'S RIGHT - RIGHT IN HERE. NOW I DON'T KNOW - A LOT OF PLANES
	HAVE SERVO DRAINS AND FUEL PORTS - I DIDN'T KNOW WHERE THAT WAS
-	

	IF I HAD KNOW WHERE THE SERVO DRAIN WAS - RIGHT HERE OR SOME-
•	WHERE LIKE THAT - I WOULD HAVE KNOWN IT WAS - BUT I THOUGHT
	POSSIBLY THEY HAD ONE THERE.
25X1A	FOR THE RECORD WE MIGHT STATE THAT AS BEING THE UNDERSIDE
	OF THE LEFT WING ROOT.
25X1A	NEAR THE TRAILING EDGE?
25X1A	;
25 <b>X1</b> A	NEAR THE TRAILING EDGE? THE FUEL
	WELL NO, I THINK IT WAS MORE ON THE FUSELAGE THAN THE WING -
	WELL I COULDN'T BE SURE BUT MY IMPRESSION, IN THAT THAT'S
	WHAT YOU WANT, MY IMPRESSION WAS IT WAS MORE ON THE BODY OF .
	THE PLANE ITSELF THAN THE WING. IT MIGHT HAVE BEEN - IT WAS
	VERY CLOSE TO THE WING ROOT - IT COULD HAVE BEEN RIGHT THERE
25X1A	WHERE THE WING JOINS.
25X1A	VERY CLOSE TO THE WING ROOT? FUSELAGE UNDERSIDE?
~	RIGHT, I COULDN'T SEE WHERE THE WING - WHERE THE ACTUAL FUEL
	Mail, I could I out within the wind - within into toke Fore

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0 WAS COMING OUT THE PLANE BUT YOU COULD SEE THE SPRAY - THE

	VAPORS FROM WHATEVER IT WAS.
25X1A	WHAT I WANTED TO DO WAS PUT THIS ON THE TAPE BECAUSE WHEN WE PLAY THIS TAPE BACK YOU WILL BE POINTING TO THIS MODEL AND SAYING IT WAS COMING FROM ABOUT HERE.
25X1A	I SEE - I THINK IT WAS MORE ON THE FUSELAGE.
25X1A	THANK YOU.
25X1A	QUESTION: -  IN PULL UP, WAS IT A ROLLING PULLUP OR DID HE  ESTABLISH THE CLIMB AND THEN ESTABLISH THE TURN OR WAS IT A  ROLLING PULLUP?
25X1A	NO SIR, THAT IS ONE THING I DEFINITELY OBSERVED, IT WAS A PULLUP
25X1A	AND THEN A ROLL.  - HE HAD STOPPED HIS PULLUP WHEN HE STARTED HIS ROLL?
25X1A	THAT'S RIGHT - IT WASN'T - IT WAS TWO DIFFERENT MANEUVERS. IT  WASN'T SIMULTANEOUS 2002/06/18: CIA-RDP74B00447R000100010065-0

THE SECRET

	QUESTION: -
	THIS SPRAY YOU SAW WAS WHITE? IT LOOKED LIKE FUEL?
25X1A	
	RIGHT LOOKED LIKE FUEL. I'VE SEEN IT CYPHEN OFF ON T-BIRDS
,	AND OTHER - IT WASN'T - MY NAV WAS TALKING ABOUT VAPOR TRAILS
	COMING OFF THE WING - I DON'T THINK IF I SAW A VAPOR TRAIL COMING
	OFF THE WING I WOULD KNOW WHAT IT WAS BUT THIS LOOKED LIKE
	FUEL TO ME SOME KIND OF LIQUID.
25X1A	
25X1A	ANY FURTHER QUESTIONS GENTLEMEN? - THANK YOU VERY MUCH.
$\smile$	
25X1A	NAVIGATOR
25X1A	I'M THE NAVIGATOR OF 25X1A
	KC 135, APPROXIMATELY 7 YEARS RATED TIME, 2300 HOURS FLYING TIME.
	ON THE 25 OF FEBRUARY I WAS INVOLVED IN AN INCIDENT WITH
	I WAS INSTRUCTED TO START FROM THE FINAL BREAKAWAY - WE HAD
	AN EMERGENCY BREAKAWAY - A PRACTICE EMERGENCY BREAKAWAY.
	AT THAT TIME WE ACCELERATED. THE U2 HAD FELL BACK. WE
	THROTTLED BACK AND I HEARD THE PILOT AND COPILOT MAKE THE
	COMMENT LOOK HERE HE COMES ON THE LEFT - ON THE RIGHT WING.
	EXCUSE ME ON THE RIGHT WING, GOT OUT OF MY SEAT STOOD RIGHT

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

AND ST. SET

BEHIND THE COPILOT'S CHAIR AND WATCHED AND WAVED. I COULD SEE THE MASK AND EVERYTHING ELSE, AND I WAS WAVING AT HIM. COMMENT WENT BACK ABOUT HIM TAKING THE JOB AWAY FROM THE BOOM OPERATOR BECAUSE HE WAS SO GOOD AND I THINK HE GAVE THE HIGH SIGN I WASN'T REAL SURE. AND AT THAT TIME HE STARTED TO CLIMB. HE STARTED A FAIRLY RAPID CLIMB BUT NOT UNUSUAL FOR THIS AIRPLANE. HE JUST STARTED TO CLIMB AND IT LOOKED TO ME AS HE STARTED TO MAKE A RIGHT TURN AS HE WAS CLIMBING. JUST A GRADUAL RIGHT TURN. AND AT THIS TIME I OBSERVED THE LEFT WING OF THE AIRCRAFT SEEMED - WELL, LET ME STOP IT AND GO BACK AGAIN. AS HE STARTED HIS CLIMB I NOTICED, I DON'T KNOW WHETHER IT WAS A CONTRAIL TYPE COMING OFF THE WING OR WHETHER IT WAS FUEL. I HAVE SEEN FUEL OR VAPORS COMING FROM THE WINGS WHEN THEY GO INTO A CLIMB A LOT OF TIMES BUT IT SEEMED SOMETHING WAS COMING FROM THE WING THERE. AND AS HE JUST - TO ME, JUST AS HE STARTED TO TURN A LITTLE TO THE RIGHT. THE LEFT WING BUCKLED RIGHT BACK ON OVER THE PART OF THE AIRPLANE. AND HE STARTED TO GO IN A SPIN OR TO ME MORE OF A WABBLING BACK AND FORTH AND I BELIEVE, I'M NOT SURE NOW, BUT I BELIEVE HIS RIGHT WING BUSTED IN HALF OR SO RIGHT IN THE MIDDLE AND THIS PART HAPPENED SO FAST, SAY IF THE RIGHT WING BUSTED, THAT THE ENTIRE AIRPLANE JUST WENT INTO A THOUSAND PIECES, JUST COM-PLETELY DISCENTEGRATED. IT WAS NOT AN EXPLOSION OR ANYTHING BUT JUST EVERYTHING FELL OFF THE AIRPLANE AND THE ONLY THING Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0 I OBSERVED LARGE WAS THE ENGINE COMPLETELY BARE WITH NO SIDING ON IT, NO NOTHING ON IT. JUST A BARE ENGINE GOING THROUGH THE AIR. THAT'S THE LAST I SAW OF IT. MY MICROPHONE WAS - - , MY BUTTON TO KEY MY SWITCH WAS SO FAR AWAY, I COULDN'T TALK. I COULD NOT REACH IT BECAUSE MY HEADSET ONLY REACHES TO THAT WINDOW, AND AT THIS TIME THE WEATHER CONDITIONS WERE PERFECT. THERE WAS NO TURBULENCE. I HAD COMPUTER TO THE WIND FOR APPLOAL-MATELY DOPPLER WIND AT ABOUT 265 DEGREES AT 65 KNOTS JUST APPROXIMATELY 2 MINUTES PRIOR TO THIS INCIDENT AND I WAS SURE AT THE TIME THAT THE MAN COULD NOT HAVE EJECTED OUT OF THE AIRPLANE BECAUSE IT HAD JUST DISCENTEGRATED. I DIDN'T SEE ANYTHING LARGER THAN - EXCEPT THIS HUGE LARGE ENGINE GO BACK LIKE IT WAS IN SLOW MOTION. AND WE PROCEEDED TO - STARTED A TURN SHORTLY RIGHT AFTER IT HAPPENED TO THE LEFT AND THERE WAS A LOT OF CONFUSION GOING BACK. THE BOOM OPERATOR CALLED UP AND SAID "I SAW HIM GO BY" OR "I SAW THE PILOT". THE PILOT CALLED AND SAID ROGER WE GOT HIS CHUTE, OUR PILOT DID, AND THE BOOM OPERATOR CALLED UP AND SAID NO, I DON'T SEE HIS CHUTE I JUST SAW HIM GO BY. AND BY THE TIME WE COMPLETED OUR 180 DEGREE TURN OR SO AND WE WERE LOOKING, WE COULD FIND NOTHING. AND THE OTHER CHASE AIRCRAFT SAID HE HAD HIS CHUTE. HE SPOTTED HIS CHUTE AND WE DID FIND HIS CHUTE AND PROCEEDED TO HOVER.

I SQUAWKED TO EMERGENCY FREQUENCY AND HOVERED IN THE AREA UNTIL WE WENT CLEAR DOWN TO 9,000 FEET AND STAYED THERE UNTIL THE COPTERS CAME UP AND PICKED UP THE MAN. THAT'S ABOUT ALL. I DON'T KNOW WHAT ELSE YOU'D LIKE ME TO GO THROUGH. I COULD SAY THAT I CAN TELL YOU THE TRUE AIRSPEED. WE WERE MAKING IN THE NEIGHBORHOOD OF BETWEEN 340 AND 350 TRUE AIRSPEED. I WOULD SAY, MAYBE CLOSER TO 345 TO 350 TRUE AIRSPEED AT THE TIME.

25X1A

THIS IS AT TIME OF INCIDENT OR DURING REFUELING?

25X1A

DURING REFUELING AT ALL TIMES WE HAD A TRUE AIRSPEED OF SAY

340 TO 350 DURING THE ENTIRE REFUELING. I CAN BE THAT EXACT ON

THE TRUE AIRSPEED. BUT WE HAD JUST FINISHED THE BREAKAWAY SO

WE MAY HAVE INCREASED BUT THEN AGAIN THE PILOTS HAD JUST

THROTTLED BACK TO, AND THAT'S WHEN HE CAME ALONG SIDE. AND

THEN WHEN HE STARTED HIS CLIMB I DO REMEMBER HE DROPPING

BACK AND UP WHEN HE STARTED HIS CLIMB. BUT IT JUST SEEMED TO

ME, WELL MY FIRST IMPRESSION, THAT THE MINUTE HE STARTED TO

TURN THE AIRPLANE TO THE RIGHT THAT'S WHEN THE WING WENT RIGHT

OVER AND IT SEEMED LIKE THE WING JUST MAYBE AN INSTANT HUNG

UP OVER THE AIRPLANE AND THEN IT CAME OFF.

25X1A

JUST PRIOR TO THAT HE WAS ACTUALLY DRIFTING BACK? HE WASN'T IN PRECISE FORMATION?

25X1A

HE WAS IN PRECISE FORMATION FOR MAYBE 30 SECONDS OR SO AND THEN AFTER THE COMMENTS WAS MADE LIKE I SAID, SOMEBODY MADE A COMMENT HE JUST SAID MORE OR LESS GOODBYE AND HE STARTED TO CLIMB AND GO AND THE MINUTE HE HE STARTED TO TURN IN HIS CLIMB THAT WING WENT RIGHT OFF. RIGHT AT THE ROOT OR WHERE IT IS CONNECTED TO THE FUSELAGE. THE WING DID NOT BREAK IN HALF OR INTO PIECES OR ANYTHING. I REMEMBER THAT.

QUESTION: -

IT WAS DEFINITELY THE LEFT WING?

25X1A

YES SIR. I'M SURE. TO MY KNOWLEDGE I'M SURE THEN AND I'M SURE NOW. I WAS VERY EXCITED. JUST COULDN'T BELIEVE IT. SEEMED LIKE A DREAM TO BE REAL HONEST WITH YOU EVERYTHING HAPPENED SO FAST. I KNOW I COULDN'T REACH MY MICROPHONE BECAUSE MY CABLE, MY CORD, DOESN'T GO OVER THERE AND THE BOOM OPERATOR, EXCUSE ME, THE COPILOT HOLLERED "HE JUST LOST A WING" AND THE PILOT SAID "WHAT WHAT WHAT". HE SAID "HE JUST LOST A WING".

I COULDN'T SAY ANYTHING - COULDN'T REACH MY MICROPHONE QUITE A BIT OF EXCITEMENT AND WHEN HE WENT INTO A THOUSAND
PIECES I KNEW THAT THAT THE PILOT WAS GONE. THERE WAS NOTHING
LEFT OF ANYTHING. I MEAN IT MAN, I SAW THE ENGINE AND THAT WAS
THE BIGGEST THING. AND I KNEW THAT HE COULDN'T HAVE GOTTEN
OUT. I KNOW NOW DIFFERENTLY BUT AT THE WAY THE AIRPLANE
WENT INTO SO MANY PIECES SO FAST - I KNEW THAT - AND ALL THE
TIME THAT I WAS WATCHING I NEVER ONCE SAW HIM GET OUT OF THE
AIRPLANE - LEAVE THE AIRCRAFT.

QUESTION: -

DID YOU SEE THE AIRCRAFT ROLL AFTER THE WING CAME OFF? DID IT SEEM TO YOU TO DO A SNAP ROLL?

25X1A

THE AIRPLANE - IT WAS REAL HAZY OR MAYBE I TURNED AWAY RIGHT AFTER IT WENT OVER OR SOMETHING OR AFTER THE COPILOT HAD - BUT IT SEEMED LIKE THAT THE AIRPLANEWAS TRYING TO GO THE RIGHT AFTER IT LOST ITS WING. AND THEN IT SEEMED TO BUST THE RIGHT WING IN HALF OR SO. IT DIDN'T COME OFF AT THE ROOT. MAYBE IT WENT INTO A LOT OF PIECES. BUT THE PART THAT I AM SO SURE OF IS THAT THE LEFT WING CAME RIGHT OFF AT THE BASE AND I KNOW THAT AERODYNAMICALLY IT SHOULD HAVE PROBABLY GONE THE OTHER WAY, IT SEEMS TO ME ANYWAY BUT IT DID AND IT

SEEMED LIKE IT WENT TO THE RIGHT AND BUSTED THE RIGHT WING
AND THEN - BUT IT WAS ALSO VERY NOSE HIGH AT THIS TIME. VERY
NOSE HIGH AND IT SEEMED LIKE IT WENT NOSE HIGHER WHEN THE NOSE
WENT A LITTLE BIT HIGHER AT THE INCIDENT IT WENT INTO PIECES
ALL OVER.

25X1A

\_\_\_\_\_\_

IT WAS NOSE HIGH PRIOR TO LEFT WING FAILURE?

25X1A

NO SEEMED LIKE WHEN IT - IT'S HARD TO EXPLAIN - AS HE WAS
CLIMBING LIKE THIS THIS IS WHAT IT SEEMED LIKE TO ME. WE WERE
ABEAM OF EACH OTHER AND HE STARTED HIS CLIMB LIKE THIS GOING
UP JUST VERY RAPIDLY WHICH IS NOT TOO RAPID FOR THIS AIRPLANE
BUT FAIRLY FAST, AND JUST SEEMED LIKE HE STARTED TO ROLL.
THIS, THE LEFT WING BUCKLED ON OVER AND THEN THIS JUST WENT
INTO PIECES ALL OVER. THE ENTIRE AIRPLANE JUST SHREDDED BUT
IT SEEMED LIKE BETWEEN THE TIME THE LEFT WING CAME OFF,
THIS BUSTED, SAY IN THIS VICINITY. HALF WAY THROUGH THE WING
A LITTLE CLOSER TO THE BAY. IT SEEMED LIKE THIS BUSTED AND
WHEN IT DID BUST, IF I CAN REMEMBER RIGHT THE AIRPLANE WAS
MORE LIKE THIS WHEN IT JUST SHATTERED. EITHER LIKE THIS OR LIKE
THIS.

25X4A

WOULD YOU SAY THAT AFTER THE LEFT WING CAME OFF AFTER HE

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

ROLLED TO THE RIGHT AND THE RIGHT WING - - -

25X1A	
25X1A	SEEMED TO ME BREAK -
25X1A	POSSIBLY IN THE MIDDLE POSITION BUT BITS AND PIECES
	A LITTLE CLOSER TO THE BASE NOT IN THE MIDDLE BUT A LITTLE
	CLOSER TO THE BASE.
25X1A	
25X1A	AT THAT TIME WHAT ANGLE WAS THE FUSELAGE AT?
	_
25X1A	I WOULD SAY NOSE HIGH.
	WHEN YOU USED THE MODEL IT WAS ABOUT 60 DEGREES
25X1A	
	WELL AFTER THE WING CAME OFF I WOULD SAY THAT SHORTLY RIGHT
	AFTER THE WING CAME OFF I WOULD SAY THAT HE WAS CLOSE TO
	60 DEGREES IT SEEMED TO ME HE WAS GOING 60 DEGREES NOSE HIGH
	AT LEAST. I DON'T KNOW HOW - THAT'S WHAT IT SEEMED LIKE TO ME.
25X1A	
	AND THIS WAS JUST PRIOR TO THE RIGHT WING BREAK?

	•
25X1A	
	NO MAYBE I REALLY COULDN'T SAY FOR SURE ON THAT, I'LL TRY
	TO GET IT. THE LEFT WING CAME RIGHT OFF. BUCKLED BACK OVER
	AND LEFT. THE RIGHT WING BUSTED AND JUST PRIOR TO THE AIRPLANE
	DISINTEGRATING IT WAS JUST NOSE HIGH 60 SOME DEGREES NOSE
	HIGH AND IT JUST SEEMED AS IF IT WAS A JIGSAW PUZZLE THROWN
	IN THE AIR. THAT'S ABOUT AS BEST DEFINITION AS I CAN GIVE. JUST
	PIECES ALL OVER.
25X1A 25X1A	COULD YOU DISTINGUISH ANY OF THE PIECES SUCH AS THE TAIL SECTION?
	NO. I COULD DISTINGUISH THE ENGINE IT WAS THE ONLY ONE AND 25X1A
	I HAVE SINCE THEN TALKED TO THE THE COPILOT, AND
	HE SAID HE DISTINGUISHED THE NOSE COMPARTMENT OF THE AIRPLANE.
	I DID NOT DISTINGUISH AT ALL. ALL I COULD NOTICE WAS THIS LARGE
	BARE ENGINE, AS I SEE WHEN WE GO TO THE AIRPLANE SOMETIME
	AND THE COWIING IS ALL OFF THE ENGINE AND EVERYTHING ELSE.

I NOTICEL THE - - - BARE ENGINE.

25×1/A

\_\_\_\_\_\_

YOU SAY AFTER THE INCIDENT OCCURED THAT THE PILOT BANKED
THE 135 TO THE LEFT - ORBITED TO THE LEFT?

25X1A

WE DID PROCEED TO MAKE A TURN TO THE LEFT, I BELIEVE, TO BE
HONEST WITH YOU I WOULD NOT GUARANTEE ON THAT. I WAS LOOKING
OUT THE RIGHT WINDOW AND LOOKING BACK AS FAR AS I COULD GO

BACK AND WHEN IT FINALLY DAWNED ON ME, - I DON'T KNOW HOW

LONG IT TOOK - WHEN IT DAWNED ON ME I JUMPED IN THE SEAT AND

TRIED TO - THERE AND NOTICED ON THE RADAR WAS BAKERSFIELD

COMING IN. ABOUT, OH, IN THE NEIGHBORHOOD OF 270 POSITION. I

DON'T EVEN REMEMBER THE EXACT MILEAGE BUT I JUMPED IN AND

TOOK A FIX OFF THE GREAT BIG TOWN OF BAKERSFIELD AND PLOTTED

IT ON MY MAP AND THERE WAS A LOT OF TALK GOING ON THE RADIO

AT THAT TIME. I BELIEVE, THOUGH, THE TURN WAS TO THE LEFT.

25X1A

I WOULD LIKE TO GO BACK TO WHAT YOU SAW JUST PRIOR TO THE LEFT WING LEAVING. CAN YOU DESCRIBE WHERE YOU SAW WHAT YOU THOUGHT MIGHT HAVE BEEN FUEL?

	•		•	
2	5	X	1	A

THROUGH, IT LOOKED AS IF IT COULD HAVE BEEN COMING FROM TWO PLACES. MAYBE THIS WAS RIGHT AT THE TIME OF THE BREAK BUT I DID NOTICE A STREAM SEEMED TO BE COMING FROM THE VERY TIP OF THE LEFT WING BUT THIS MAY HAVE BEEN - MAYBE THE WING HAD ALREADY ACTUALLY BUCKLED, BUT I DID NOTICE LIKE A STREAMER LIKE YOU WOULD SEE A FIGHTER OR WHAT DO THEY CALL IT - A CONTRAIL OR A VAPOR TRAIL WHEY YOU MAKE A REAL SHARP TURN OR SOMETHING TO THIS EFFECT? THIS WAS, SAY, RIGHT AT THE INSTANT THAT THE WING HAD COME OFF. AND I NOTICED, I WOULD SAY, IN THE THIRD OR CLOSE TO THE ROOT OF THE WING, EITHER FUEL OR SOME TYPE OF VAPOR COMING FROM THERE.

25X1A

25X1A FIRE?

NO FIRE. I NEVER ONCE SAW FIRE, SMOKE, OR ANYTHING DURING THE ENTIRE THING.IT'S REAL FUNNY.

QUESTION: -

COULD YOU POINT ON THAT AIRPLANE MODEL WHERE YOU SAW THE

FUEL COMING FROM? AND THEN WILL DESCRIBE HER. 25

25X1A

HOW'S THAT?

25X1A

WELL, AS I SAID, I WAS NOT SURE IT WAS FUEL. I WOULD NOT GUARANTEE THAT IT WAS A FUEL. IT MAY HAVE BEEN - WHAT IS THE EXACT WORD YOU FIGHTERS USE YOU CAN SEE THEM WHEN THEY COME IN.

25X1A	
	CONDENSATION TRAIL.
25X1A	
25X1A	WHERE HE MAKES A REAL SHARP TURN - THE STREAMER TYPE?
	_
	VORTEX.
25X1A	
	VORTEX. I THINK THAT'S THE WORD I WAS THINKING OF. VORTEX.
	IT MAY HAVE BEEN VORTEX FROM THE VERY TIP, THE LEFT TIP OF
	THE WING. BUT IN THE FIRST THIRD SECTION, IN THROUGH HERE,
	WHEN HE WAS GOING UP LIKE THIS - THE THIRD - SAY YOU DIVIDE THE
	WING INTO THREE SECTIONS - THE THIRD CLOSEST.
	QUESTION: -
	THIS IS WHEN HE IS STILL IN THE CLIMB AND AND NOT IN THE RIGHT
25X1A	TURN?
	WELL, THIS IS RIGHT IN THE TWO - I SHOULD SAY THE LAST PART -
	THE VERY LAST PART OF HIS CLIMB BEFORE HE STARTED HIS LEFT
	TURN. I COULD SEE COMING FROM THIS PART OF THE WING - VAPOR
	TYPE.

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0
WAS IT A VERY THIN STREAM?
Y 3.0 II 21 VIII I IIII SIREIMI.
YES
· ·
QUESTION:
POINT TO WHERE IT WAS COMING FROM AT THAT TIME.
IN THIS AREA IN HERE IS THE ONLY PART I COULD SAY - CLOSER TO THE
TWO.
BUT IT WAS DEFINITELY FROM UNDER THE WING?
WELL, SEE I WAS IN THIS POSITION AND I COULD SEE IT COMING OUT HERE
IN THIS CLOSE PROXIMITY TO THE FUSELAGE.
SO IT APPEARED TO BE FROM THE UNDERSIDE OF THE INNER THIRD OF THE
WING.
RIGHT. I COULD NOT SEE THE UPPER SIDE OF THE WING AND I COULD
JUST SEE IT COMING OFF OF BACK HERE. IT COULD HAVE BEEN RUNNING
OFF OF THE TOP OR IT COULD HAVE DOING THIS TOO. I DON'T KNOW.
YOU COULD SEE THE WHOLE AIRPLANE AT THAT TIME?
YES, AT AN ANGLE LIKE THIS I COULD SEE THE WHOLE AIRPLANE, YOU KNOW
WHAT I MEAN, STAYING OUT HERE LIKE THIS - THE SIDE VIEW OF IT - I  Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0
Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

25X1A	Page 86  Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0
25X1A	ALMOST LOOKING TIP TO TIP.
•	TEMOST LOCKING TIP TO TIP.
	RIG'IT, BUT WHEN HE WENT LIKE THIS THERE SEEMED TO BE A LARGE GUSH
25X1A	OF FUEL AS THE WING WENT OVER - LARGE GUSH OF FLUID RIGHT IN HERE
25X1A	WAS IT A SHEET? YOU SAY IT WAS A SHEET?
	RIGHT. LIKE A BALLOON FULL OF WATER POPPING AT ONE TIME MAYBE
	BUT THAT WAS AS THE WING BROKE.
25X1A	7
	IF I MAY, I WOULD LIKE TO POINT OUT THAT WE HAVE A VENT LINE UP HERE
	IN THE TOP OF THE FIN - IS THERE ANY POSSIBILITY THAT THIS VAPOR YOU
25X1A	SAW MIGHT HAVE DEEN COMING FROM THAT AREA OF THE AIRPLANE.
	I REALLY COULDN'T SAY TO BE HONEST WITH YOU - I DO NOT BELIEVE IT
	CAME FROM THERE BUT AGAIN MAYBE THE ANGLE AND SEEING THE STREAM
	IT DID SEEM TO COME FROM THAT WING THO I WILL HAVE TO SAY.
	DID SEEM LIKE COMING FROM THE WING. THERE IS A POSSIBILITY THAT IT
	COULD HAVE COME FROM THE VENT BUT I STILL SAY FROM THE WING. I
	WAS SO AMAZED WITH THE FACT THAT EVERYTHING WAS HAPPENING SO
	DOGGONE FAST THAT IT SEEMED SIMILAR TO A DREAM.

_	_	٠,		
ソ	っ	Х	1	Δ

25X1A

WINDOW.

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-Dage 87

	COULD YOU GIVE US, TO THE BEST OF YOUR ABILITY, THE ACTUAL LOCATION
	WHEN THE INCIDENT OCCURRED - IN OTHER WORDS YOU GOT BEARINGS OFF
25X1A	BAKERSFIELD AND YOU GOT BEARINGS OFF PALMDALE, I BELIEVE.
	RIGHT. I TOOK A RADAR BEARING OFF OF BAKERSFIELD AND I BELIEVE THE
	COORDINATES WERE 35 22 NORTH - I WOULD HAVE TO GET MY CHART TO
	DOUBLE SURE BUT I'M SURE THE 22 NORTH IS GOOD AND I BELIEVE 118 19
	WEST IS WHAT I BELIEVE. I THINK IT WAS BETWEEN 17 and 19 WEST -
	IS WHERE THE POSITION THAT I TOOK RIGHT AFTER I JUMPED PACK AND
	ADJUSTED SAY FOR 30 SECONDS OR WHATEVER IT WOULD BE - THIS IS MY
25X1A	POSITION.
¥)	
25X1A	YOU ADJUSTED IT BACK?
	RIGHT - THIS IS WHAT I DID. I JUST PLOTTED IT, JUST MOVED IT BACK
25X1A	MAYBE
25X1A	DO YOU RECALL WHAT YOUR PEARING WAS WHEN THE INCIDENT OCCURRED?
	NO, I DIDN'T, AT THE TIME THE INCIDENT OCCURRED I WAS STANDING
	BEHIND THE COPILOTS SEAT AND I HAD BEEN THERE SAY APPROXIMATELY
	30 SECONDS. I HAD BEEN BEHIND THE COPILOT AND LOOKING OUT THE

WILAT Approved for Wellease 2002/06/18 T CIA-RDP74B00447R000100010065-0

WE WERE ON A MAGNETIC HEADING OF 33 CORRECTION, CORRECTION 183.

MAGNETIC HEADING NUMBER 183. WE WERE MAKING A GROUND SPEED OF

340 KNOTS AT THAT TIME. AND I HAD A DOPPLER WIND JUST PRIOR TO THE

INCIDENT OF 265 DEGREES, 60 KNOTS, 60 KNOTS

0	E	V	1	٨	
2	ວ	Л	- 1	А	

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065 9e 89

25X1A

YEAH, I THOUGHT THAT - COULD I ADD THAT YOU GAVE THAT OVER THE RADIO AND WHEN YOU FIRST MENTIONED, YOU SAID 265, 65.

25X1A

25X1A

I BELIEVE 1 DID SAY 65. I'LL DOUBLE CHECK ---

AND YOU TOOK A RADAR FIX OFF BAKERSFIELD?

1 HAD A RADAR FIX OFF OF BAKERSFIELD AT 1816 WHICH WAS RIGHT. 2 MINUTES - WHAT I WOULD FIGURE WAS APPROXIMATELY 2 MINUTES PRIOR TO THE INCIDENT - THE ACTUAL INCIDENT HAPPENING AND AT 1816 I HAD PLATNED TO MAKE A 180 DEGREE TURN TO THE LEFT CAUSE THIS WAS OUR ACTUAL TURNING POINT AND I HAD PLANNED TO TURN 180 TO THE LEFT AND AT 1816 HE DECIDED HE WAS GOING TO GET ONE MORE CONTACT AND I WAS TALKING WITH THE PILOT BACK AND FORTH AND I SAID WELL, LET'S GET OUT OF HERE - THEY DON'T WANTUS TOGOSOUTHOF A CERTAIN LINE I HAD PLOTTED IT ON MY CHART AND HE SAID WHAT'S THE LATEST WE COULD GO AND I SAID WELL, WE BETTER TURN BY 18 AFTER ....... THAT'S GETTING AS CLOSE AS WE'D WANT TO GO TO THAT LINE AND ABOUT APPROXIMATELY 1817 I'D SAY ME HOOKED UP AGAIN AND I SAID WELL, LET'S GET TIM OFF AND GET OUT OF HERE - TO THE LEFT - I DON'T WANT TO GET INTO ANY RESTRICTED AREA HERE. - OR GET HIM FURTHER SOUT! OF THE LINE AND APPROXIMATELY 1818 OR SAY 1817 AND 30 SECONDS HE DISCONNECTED WITH EMERGENCY - PRACTICE EMERGENCY BREAKAWAY AND PULLED ALONG OUR RIGHT WING AND STAYED THERE FOR 30 SECONDS

AND THEN STARTED THIS CLIME WHEN THE INCIDENT HAPPENED.

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

#### Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

25X1A

COULD YOU STATE YOUR ESTIMATE IN LAT AND LON.

25X1A

LATITUDE AND LONGITUDE?

25X1A

YEAH

WHAT I GAVE YOU WAS 3522 NORTH 118 17 - THIS IS THE 118 17 WEST WAS MY POSITION THE DAY OF THE INCIDENT. SINCE THEN USING MY TRACK I FIGURE ABOUT A 118 20 WEST WOULD BE A LITTLE CLOSER. BUT THE LATITUDE OF 3522 NORTH SHOULD BE, TO THE BEST OF MY KNOWLEDGE RIGHT THERE WHERE THE ACTUAL INDICENT OCCURRED.

25X1A

ANY FURTHER CUESTIONS GENTLEMEN:

QUESTION:

DID YOU NOTICE ANY FLEXING OF THE WING PARTICULARLY WHILE HE WAS OUT FLYING ALONG WITH YOU IN FORMATION?

25X1A

I NOTICED WHEN I FIRST LOOKED OUT, MAYBE - I PROBABLY SHOULDN'T
HAVE EVEN BROUGHT T'ES UP BECAUSE IT MIGHT BRING SOME QUESTIONS IT SEEMED TO ME JUST WHEN HE WAS JUST COMING ALONG OUR LEFT WING
THAT HE GOT JUST LIKE ONE LITTLE BOUNCE ----- HOW THE WINGS WILL
FLEX BECAUSE OF THEIR LENGTH, YOU KNOW, ANY TYPE OF LITTLE
BOUNCE OR ANYTHING YOU SEE - IT LOOKED TO ME LIKE HE BOUNCED ONCE
AND THEN EVERYTHING WAS PERFECTLY STABLE. WE HAD A VERY STABLE
PLATFORM. WE WERE FLYING 200 INDICATED AT OUR TIME AND REAL
Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

ACCURATE FIE EVEN MADE THE COMMENT - THE PILOT MADE THE

	Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0 COMMENT OF HOW ACCURATE IT WAS. BUT WHEN THE U BIRD DID PULL
	/ LONG SIDE THE WING - ACTUALLY LIKE HE WAS CATCHING UP WITH US
	JUST A LITTLE BIT - WE WERE THROTTLING BACK AND I UNDERSTAND
	HE WAS JUST CATCHING UP WITH US - AND ONE LITTLE RIPPLE, I PROBABLY
	SHOULDN'T EVEN MENTION THAT - JUST A MINOR LITTLE BOUNCE MAYBE.
25X1A	
25X1A	AND THEN HE STAYED IN FORMATION FOR ABOUT
	THEN HE STAYED IN FORMATION FOR ABOUT 30 SECONDS I'D SAY. THAT'S
	JUST A GUESS - BY THE TIME I GOT OUT OF MY SEAT, HE WAS THERE MAYBE
	HE WAS THERE 30 SECONDS. HE KEPT WAVING BACK AND FORTH - I WAS
	TRYING TO WAVE AT I'IM.
25X1A	
<u> </u>	DID YOU NOTICE THE SPEED PRAKES COME OUT OR DID YOU JUST NOTICE
25X1A	THEM TO BE GUT?
25X1A	I DID NOT NOTICE THEM AT ALL - I REALLY DID NOT.
25X1A	I SEE.
	BUT I DO KNOW WHEN HE STARTED - JUST SAY AT THE TIME HE STARTED THE
	CLIME OR JUST PRIOR TO THE TIME HE WAS CLIMEING HE STARTED TO
25X1A	DROP BACK - PROCEEDED TO CLIMB RIGHT UP DIRECTLY.
	ASIDE FROM THE VAPOR INDICATIONS AND PRIOR TO THE WING FAILURE -
	THERE WAS NOTHING THAT YOU WOULD SAY WAS UNUSUAL ABOUT THE

 ${\it AIRPLA}$  Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

Page	92
------	----

25X1A	Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0
	NO, NOTHING AT ALL UNUSUAL - IT WAS PERFECTLY NORMAL AND
25 <b>×4</b> A	EVERYTHING SEEMED TO BE PERFECTLY NORMAL.
	NO INDICATIONS OF ANY FAILURE OR ANYTHING PRIOR TO THE LEFT WING
25X1A	FAILURE.
25X1A	NO, NOT AT ALL.
25X1A	YOU'VE WITNESSED OTHERS OF THESE
25X1A	YES I HAVE.
•	THIS SORT OF PROCEDURE - DID THE CLIMB APPEAR TO BE NORMAL?
25X1A	WHAT YOU HAVE SEEN BEFORE?
	LET ME CLARIFY ONE THING - I'VE WITNESSED QUITE A FEW TAKEOFFS
	FROM THE GROUND AND HAVE BEEN OUT THERE WHEN THEY HAVE TAKEN
	OFF FROM THE GROUND - I BEING THE NAVIGATOR, THEY PUT YOU BACK
	IN THE RADAR SET AND ABOUT THE TIME THEY DISCONNECT THEY USUALLY
	WILL PULL ALONG SIDE OR SOMETHING AND START THEIR CLIME AND I
	USUALLY DONT WITNESS THOSE CLIMBS - ACTUALLY IN THE ALTITUDE -
	BUT I HAVE SEEN THEM CLIMB FROM THE GROUND ON UP AND HE DIDN'T
	GO ANYTHING QUITE LIKE THAT - IT WAS JUST A - RATHER FAST CLIMB
	FOR OUR TYPE OF AIRCRAFT, WHICH IS A KC135 - WE COULDN'T DO IT THAT

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0 HIP STREET

FAST. I WOULD ASK - I WAS TRYING TO TALK WITH ONE OF THE OTHER

	Page 93  Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0  CREW MEMBERS AND WOULD SAY 500 FEET HE CLIMBED JUST QUICK
÷ /	LIKE THAT - REAL QUICK LIKE THAT - HE WAS 500 FEET ABOVE US -
	MAYBE TO A 1000 FEET ABOVE US WHEN THE INCIDENT ACTUALLY
25X1A	OCCURRED.
	YOU WERE LOOKING DOWN THEN AND PEERING UP OUT OF THE WINDOW?
25X1A	:
	YES, FROM THE TIME HE STARTED HIS CLIMB UNTIL THE TIME THE WING
	CAME OFF I MADE A COMMENT LIKE GEEZ"LOOKIT, THERE HE GOES"-
	SOMETHING LIKE GEEZ THERE HE GOES AND THEN HE STARTED TO GO UP
	AND I HAD TO GO DOWN - HAD TO PUT MY HEAD WAY DOWN TO THE BOTTOM
	PART OF THE WINDOW SO I COULD SEE HIM - AND THEN SAW THE WING COME
25X1A	OFF. AND THE TRAIL.
	DID YOU AT ANY TIME LOSE SIGHT OF HIM WHILE HE WAS GOING THRU THAT
25X1A	CLIMB?

NO, NOT TO MY KNOWLEDGE. I BELIEVE AFTER THE WING CAME OFF I MIGHT HAVE TURNED AND TRIED TO HELP THE PILOT GET THE IDEA THAT THE WING CAME OFF BECAUSE THE COPILOT HAD MENTIONED IT AND HE HOLLERED "WHAT" AND I MIGHT HAVE TURNED THEN AND SAID "THE WING CAME OFF" AND CAME BACK AND SAW IT LEAVE THE AIRPLANE AND DIS-INTEGRATE.

25X1A

THANK YOU VERY MUCH FOR YOUR INFORMATION

BOOM OPERATOR, :

25X1A

25X1A

 $I^{!}\,M$ BOOM OPERATOR ON THE KC 135 AIRCRAFT. CONVERNING THE ACCIDENT, I WAS IN THE BOOM POD WATCHING THE CONTRAILS FROM THE UZ AIRCRAFT AND I HEARD THE COPILGT STATE HE'S LOST A WING. ALMOST INSTANTLY I SAW HIS DEBRIS AND OUT OF THIS THE PILOT. I WATCHED THE PILOT AS LONG AS I COULD-WAITING FOR THE CHUTE TO DEPLOY. WE MADE A TURN AND I LOST SIGHT OF HIM. ON THE CONTACTS - IT WAS THE SMOOTHEST CONTACTS I'VE EVER SEEN. HE MADE 9 CONTACTS. I LINED THE BOOM UP, YOU KNOW, AND HE ACTUALLY MADE THE CONTACTS HISSELF. REAL EASY -REAL SMOOTH. IN FACT, ITS THE BEST I'VE EVER SEEN ON AN AIRPLANE. IN FACT I WOULDN'T GIVE ANY TRAINING AT ALL, I WAS JUST HOLDING THE BOOM, YOU KNOW, AND HE WAS MAKING THE CONTACTS. DURING THE CONTACTS THERE WASN'T ANY MOVEMENT IN AZIMUTH AT ALL AND TWO OR THREE TIMES HE MADE A COUPLE OF MOVES UP AND DOWN - JUST A LITTLE - ENOUGH I COULD - I COULDN'T FEEL IT IN THE CONTROLS OF THE BOOM BUT I COULD FEEL IT IN THE AIRPLANE, YOU KNOW, AS IT KINDA FELT LIKE IT WAS SLOWING DOWN AND COMING FORTH - THE WINGS DIDN'T FLEX -I DIDN'T SEE ANY MOVEMENT OF THE WINGS.

25X1A

WAS THERE ANYTHING UNUSUAL ON ANY OF THE DISCONNECTS AT ALL?

25X1A	
	P

### Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065P0age 95

NO. EITHER THE PILOT OR I MADE THE COUNT FOR THE DISCONNECTS EXCEPT ONE TIME WHEN HE DISCONNECTED AND BACKED OFF AND WE DIDN'T COUNT - OTHER THAN THAT - EVERYTHING WAS NORMAL AND THE 25X1A BESTI VE EVER SEE. 25X1A DID YOU, ON ANY OF THE CONNECTIONS, TRANSFER ANY FUEL? 25X1A NO SIR. NO FUEL WAS TRANSFERRED WHATSOEVER. DID YOU NOTICE ANY FUEL VAPOR ON THE BREAKAWAY OF ANY OF THE DISCONNECTS? NO. WE HAD JUST A LITTLE FUEL VAPOR AROUND THE NOZZLE WHEN WE MADE CONTACT. BUT I THINK IT WAS RESIDUE FROM THE - JUST A LITTLE ACCUMULATION EITHER IN THE BOOM OR WHEN HE OPENS - I SUPPOSE HE HAS A VALVE HE OPENS - POSSIBLY CAME OUT. 25X1A THAT WAS ONLY ON THE CONTACT, RIGHT? 25X1A ONLY ONE CONTACT - IN CONTACT - IT WAS JUST ENOUGH TO MAKE THE BACK PART OF THE FUSELAGE FOR ABOUT A FOOT BEHIND THE RECEPTACLE DAMP. YOU COULD SEE THAT THE FUSELAGE ......

CAN YOU SEE THESE LITTLE DOORS WHICH - ON EITHER SIDE OF THE TOP

FUSELAGE WHICH CLOSE OR SHOULD BE CLOSED WHEN REFUELING TAKES

LOSE OR SHOULD BE CLOSED WHEN REFUELING TAKES ease 2002/06/18: CIA-RDP74B00447R000100010065-0

## Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0 age 96

	••
	PLACE OR WHEN THAT RECEPTACLE IS OPEN. THESE
	THERE ARE TWO LITTLE DOORS HERE WHICH SHOULD BE CLOSED - YOU
25X1A	DIDN'T NOTICE ANY OPENING?
25X1A	THERE WAS NO DOORS OPEN.
	NO DOORS OPEN - THEY'RE ABOUT NOT MUCH BIGGER THAN THAT
	COMMENT:
25X1A	6 INCHES LONG AND ABOUT THAT - THAT WIDTH
	:
25X1A	FINE.
	·
	AT ANY TIME, WHEN YOU WERE WATCHING THE U BIRD, DID YOU NOTICE
	ANY FUEL ESCAPE FROM ANY PART OF THE AIRPLANE?
25X1A	
	NO SIR. THERE WASN'T ANY SPRAY, VAPOR OR ANYTHING OTHER THAN THE
	SLIGHT DAMPENING ON THE BACK OF THE FUSELAGE HERE, NEAR THE BOOM
	OTHER THAN THAT THERE WASN'T ANYTHING UNUSUAL.
	QUESTION:
	ON THIS LAST BREAKAWAY AS HE MOVED OUT - COULD YOU DESCRIBE
	THAT - DID HE DROP BACK AND THEN HE PULLED OFF TO THE RIGHT OR HOW
25X1A	DID HE MOVE OUT OF POSITION?
	WHEN HE CALLED BREAKAWAY, DISCONNECT AND RETRACTED BOOM AND
	MOVED OUT HIS WAS, HE SIMULTANEOUSLY - HE DROPPED BACK AND DOWN.
	IT WAS REAL SMOOTH AND I THOUGHT A GOOD DREAKAWAY. OF COURSE, Approved For Release 2002/06/18; CIA-RDP74B00447R000100010065-0
	WE DIDN'T MAVE ANY CAPAMILITY FOR MOVING FORWARD AT THAT LOW

HNG

AIR SPEED BUT WHEN HE BROKE FROM THE BOOM HE DROPPED BACK
ABOUT 50 OR 60 FEET AND ON THE FIRST INITIAL BREAK AND AFTER THAT
HE MOVED BACK A LITTLE FURTHER AND MOVED OVER TO THE SIDE
QUESTION:
YOU DIDN'T NOTICE HE GOT IN ANY TURBULENCE AT THAT TIME OR ANYTH
NO SIR. HE DIDN'T MAKE ATTY ROUGH MOVEMENTS OR ANYTHING ON THE
BREAKAWAY. LIKE THE E47 AND B52 AND SO FORTH, YOU KNOW, THEY
NOSE IT DOWN AND DROP EACK BUT TO ME HIS BREAKAWAY WAS REAL
SMOOTH. I DIDN'T SEE ANYTHING WRONG WITH IT.
COULD YOU ESTIMATE THE TIME FROM WHEN YOU LAST SAW HIM TILL
YOU HEARD A VOICE SAY HE'S LOST A WING?
IT WOULD HE'VE TO BE AN ESTIMATION SIR, BECAUSE I DON'T HAVE ANY
IDEA HOW LONG THIS WAS. I'D HAVE TO RUN A CHECKLIST AND STOW
THE BOOM - IT COULD HAVE BEEN 5 MINUTES OR 4
WHEN DID HE ACTUALLY I BEG PARDON.
GO AHEAD - YOU GO RIGHT AHEAD
WHEN DID HE DISAPPEAR FROM YOUR VIEW AS HE CAME ALONG SIDE ?

AFTER THE BREAKAWAY?

25X1A

25X1A

25X1A

25X1A

25X1A

25X1A

25X1A	Approved For Release 2002/06/18 : பிசிரிந்ரிர்க்கு 200447R000100019965-98
 25X1A	YES, AFTER THE BREAKAWAY. HOW MUCH CAN YOU SEE OUT TO THE SIDE?
	I CAN SEE HIM TILL HE GETS - OH ABOUT A 45 DEGREE ANGLE I SUPPOSE
25X1A	FROM THE BOOM POD - IT'S ACTUALLY BETWEEN MY POD AND THE WING WHEN HE GOES OUT OF SIGHT - THE WING OF THE AIRPLANE.
25X1A	I SEE.
	IN FACT, I WAS WATCHING HIS CONTRAIL WHILE HE WAS SITTING OFF THE WING OVER THERE BECAUSE I CAN PICK HIM UP IF HE MOVES BACK BY
<u> </u>	WATCHING HIS CONTRAIL, YOU KNOW, THE MINUTE HE MOVES BACK WITHIN MY SIGHT I CAN PICK HIM UP AND THAT'S WHAT I WAS WATCHING WHEN THE
25X1A	INCIDENT
25X1A	FROM WHAT POINT ON THE AIRPLANE WERE HIS CONTRAILS?
	THEY WAS THE CONTRAILS OF THE ENGINE QUESTION:
25X1A	WERE YOU WATCHING HIS CONTRAILS AT THE TIME THEY SAID HIS WING CAME OFF?
	YES SIR.
	QUESTION:  DID YOU SEE ANY DISCOLORATION IN CONTENT OF ANY CHANGE IN THE  Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

NORMAL COLOR CONTRAILS AT ANY TIME?

## Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0Page 99

25X1A	
	NO SIR, I DIDN'T.
25X1A	
25X1A	WHAT WAS THE FIRST PART OR PIECE THAT YOU SAW?
	WELL, I SAW - THERE WAS ALL KINDS OF DEBRIS - LIKE I SAY - OUT OF THIS
	CAME THE PILOT AND THEN IT WAS A LARGE SECTION OF IT WHICH I DIDN'T
	ASSOCIATE AS MEING A WING UNTIL I TALKED WITH THE 33 PILOT AFTER-
	WARD, THE MINUTE I SPOTTED THE PILOT - ACTUALLY I SPOTTED THOSE
	TWO - THE PILOT AND THE LARGE SECTION AT THE SAME TIME. WHEN
	I IDENTIFIED THE PILOT IN MY MIND THATS THE ONLY THING I WATCHED
	EXCEPT, YOU KNOW, OUT OF THE CORNER OF MY EYE I COULD CATCH THIS
	WING, YOU KNOW, AND I BELIEVE NOW THAT THAT WAS THE WING SINCE
25XTA	I TALKED TO EM ABOUT IT.
	JUST ONE LARGE PIECE AND THE PILOT AND THE REST BITS AND PIECES?
25X1A	
25X1A	THATS RIGHT.
25X1A	WAS THE PILOT STILL IN THE SEAT?
	YES SIR, HE WAS IN A SITTING POSITION WITH HIS KNEES PULLED UP UNDER
	HIM - IS WHAT IT LOOKED LIKE TO ME - HIS BACK WAS TO ME. LIKE YOU

WERE SITTING IN A CHAIR OR SOMETHING.

25X1A	Page 100 Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0
**************************************	COULD YOU ESTIMATE A TIME FROM THE PERIOD WHEN YOU HEARD HE HAS
25X1A	LOST THE WING TO A TIME YOU SAW THE PILOT? JUST A ROUGH ESTIMATE
25X1A	IT WAS PRETTY QUICK - IT WAS ALMOST INSTANTLY.
25X1A	WAS THE PILOT ABOVE OR BELOW YOUR LEVEL WHEN YOU SAW HIM.
	ABOUT EVER WITH MY EYESIGHT LOOKING OUT THE POD. I FIRST SAW
	SOMETHING AND I GOT A LITTLE OBSERVATION WINDOW ON MY LEFT,
	WHICH IS ON THE RIGHT SIDE OF THE AIRPLANE OTHER THAN THE BIG
	SIGHTING WINDOW TO LOOK OUT AND I SAW SOMETHING COME BY IT FIRST
	OUT OF THE CORNER OF MY EYE AND THEN IT CAME INTO THE BIG WINDOW.
	AND ACTUALLY TO ME IT LOOKED LIKE HE COME ACROSS BEHIND ME AT AN
25X1A	ANGLE - APPARENTLY ME WAS GOING STRAIGHT AHEAD.
	:
25X1A	COMING TOWARDS YOU OR TOWARDS YOUR TRAIL?
	ACROSS ME AT AN ANGLE, YOU KNOW, LIKE COME ACROSS IN FRONT OF ME.
25X1A	I'M LAYING DOWN LOOKING OUT, YOU KNOW
25X1A	I SEE
	I WATCHED THE PILOT UNTIL - I DONT KNOW - IT SEEMED LIKE TO ME
	10 MINUTES - I SUPPOSE IT COULDN'T HAVE BEEN VERY LONG BUT I KEPT
	PRAYING FOR THE CHUTE TO OPEN, YOU KNOW, I KEPT WAITING AND Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

WAITING. I WAS AFRAID IN THIS DEBRIS, YOU KNOW, I WAS AFRAID HIS

	Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0 CHUTE WAS TORE UP TOO AND I SAW SMOKE OR DUST - HE WAS ALMOST OUT O
	SIGHT WHELL I SAW SMOKE OR DUST AND I BELIEVE THAT WAS THE CHUTE
	WHEN IT STARTED TO OPEN. THE DUST - THE POWDER IS LOCATED IN
	THE I LOST SIGHT OF HIM AT THAT TIME AND THEN WHEN WE MADE
25X1A	A TURN, THE 180, WE SAW HIS CHUTE DEPLOYED.
25X1A	DID YOU SEE HIM SEPARATE FROM HIS SEAT AT ALL?
	WELL, THERE WAS A - BESIDES THAT WING THERE WAS OTHER PIECES
	AROUND HIM AND IT LOOKED LIKE SOMETHING ABOUT THREE TIMES
	SEPARATED FROM HIM, YOU KNOW.
25X1A	:
25X1A	I SEE
	I SUPPOSED IT WAS THE SEAT, ONE OF THE TIMES THAT I SAW - I SUPPOSE
25X1A	IT WAS WHEN THE SEAT SEPARATED FROM TUM.
25X1A	DID YOU NOTICE ANY FIRE?
	$\cdot$
25X1A	NO - NO FIRE AT ALL.
	NO FIRE AT ALL.

DID YOU EVER SEE THE ENGINE?

QUESTION .

25X1A

NO SIR, I DIDN'T. I DIDN'T SEE THE ENGINE.

25X1A	Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-9 1 02
	WAS ANY OF THIS BEDRIS THAT WAS IN THE PROXIMITY OF THE PILOT
25X1A	CLOSE ENOUGH TO HAVE STRUCK HIM WHILE HE WAS STILL IN THE AIR?
	I THINK IT WAS ALL AROUND HIM. WHEN I SPOTTED HIM, THE DEBRIS WAS
	ALL AROUND HIM - PLL JUST HAVE TO SAY IT IN MY OWN WORDS - IT
05744	LOOKED LIKE HE KINDA OUT RAN THE DEBRIS THERE FOR A SECOND OR T
25X1A	AND THATS WHEN I SPOTTED HIM.
25X1A	WAS HE DIGGER THAN ANY OTHER PIECE OF DEBRIS?
	EXCEPT THE ONE OTHER OBJECT THAT WAS - I DON'T KNOW WHETHER IT
	WAS JUST BELOW HIM OR JUST BETWEEN ME AND HIM, BUT IT LOOKED
25X1A	LOWER THAN HIM AND IT WAS FAIRLY LARGE - I BELIEVE
	JUST THE ONE PIECE, THOUGH THAT WAS ACTUALLY FIGGER THAN HIM,
25X1A	THAT YOU SAW?
25X1A	I BELIEVE THAT WAS THE WING - NOW SINCE I
25X1A	I SEE.
	DURING ALL OF THESE HOOKUPS DID YOU HAVE VAPOR TRAILS?

# Page 103 Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

25X1A		
•	RIGHT SIR - TO THE PEST OF MY KNOWLEDGE - ONCE I HOOK UP I GO ON	
	INSTRUMENTS AND WATCH HIM AT THE SAME TIME AND I DON'T WATCH	
	THE CONTRAILS THEN.	
25X1A		
	BUT YOU AT NO TIME SAW ANY VAPOR TRAIL FROM ANY PLACE OTHER TH	ΑN
	THE CONTRAIL OF THE ENGINE?	
25X1A		
	NO SIR.	
25X1A		
25X1A	ON THIS CONTACT, ONCE YOU STATED YOU SAW A LITTLE	
	FUEL VAPOR THE ONE CONTACT - DO YOU REMEMBER WHICH ONE THAT	
25X1A	WAS? WASIT	
25X1A	THE FIRST ONE.	
	THE VERY FIRST? ALRIGHT THANK YOU.	
	DO YOU HAVE ANY FURTHER QUESTIONS GENTLEMEN?	
	QUESTION:	
25X1A	DO YOU HAVE ANY QUESTIONS STEVE?	
	WELL THANK YOU VERY MICE. 25X1/	А

### Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

25X1A	TALLE DISCUSSION WITH TANKER CREW
~	
	TO MY KNOWLEDGE JUST AS PCSITIVE AS I CAN BE
25X1A	:
25X1A	WASN'T QUITE AS SURE, WE THOUGHT THAT
	WELL, HE SAID IT WAS THE LEFT WING, HE DID SAY IT WAS THE LEFT WING,
	WHEN HE SAID THE WING WAS COMING OFF AND THEN WHEN I ASKED HIM
	"WHAT!" AND HE SAID - THE WING IS COMING OFF - ITS DISINTEGRATING.
	COMMENT:
25X1A	ALL THE SIGHTINGS SEEM TO BE QUITE FAIRLY CONSISTENT
	:
	BEFORE WE GOT DOWN YESTERDAY, WITHIN AN HOUR, I WAS SURE IT WAS
	THE LEFT WING TOO AND SOMEONE SAID, WE WERE DEBRIEFING - MAKING
25X1A	STATEMENTS AND SOMEONE SAID NOW LOOK AT THE
25X1A	
25X IA	AERODYNAMISISTS, DO WE HAVE ONE AVAILABLE?
	WHAT WOULD HAPPEN? THATS WHAT WE WHAT WOULD HAPPEN
	IF THE WING CAME UP AND IT CAME COMPLETELY OFF AND YOU LOST ALL
	THE DRAG YOU GOT ONE WING AND YOU WERE IN SAY APPROXIMATELY
	THIS ATTITUDE - DO YOU GET MORE LIFT TO MAKE IT COME BACK THIS
	WAY OR DO YOU GET MORE DRAG TO CONTIMUE IT ON OVER? IF IT HAD
$\smile$	ALREADY HAD A ROLLING MOMENTUM TO IT AT THE TIME THAT THE

WING CAME ..... I MEAN - REALIZE THERE'S NO DRAG EFFECT ON THIS

WING, I Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0 WING, I Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0 Page 105
AIRPLANE - WOULD IT CONTINUE ROLLING IN THIS DIRECTION OR TO

25X1A DISINTEGRATE?

YOU HAVE TWO, I THINK, COUNTERACTING FORCES HERE, ACTUALLY I
THINK TWO THINGS WOULD HAPPEN AT THE SAME TIME. THERE WOULD
BE THE IMMEDIATE TENDENCY FOR IT TO ROLL TO THE LEFT, BUT ALSO
A VERY FOND TENDENCY FOR IT TO YAW TO THE RIGHT.

25X1A

TO THE RIGHT.

25X1A

THAT'S WHAT I GIFURED, HE WOULD HAVE DRAG.

DEPENDING ON HOW MUCH IT YAWED, ACTUALLY, I WOULD SAY - IT'S VERY DIFFICULT TO DEFINE - TO SAY WHAT IT WOULD DO AT THAT SPEED.

ONE MIGHT COUNTERACT THE OTHER. THE FACT THAT IT WOULD YAW TO THE RIGHT WOULD COUNTERACT THE FACT THAT THE WING WAS TRYING TO ....

25X1A

:

25X1A

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

Page 106 Approved For Release 2002/06/18: CTA-RDP74B00447R000100010065-0 HAVE BEEN THE TOP WING THAT WAS GOOD - TO GIVE YOU THE LIFT TO CARRY IT ON OVER. AND THEN AFTER WE TALKED ABOUT IT A WHILE HE SAID WELL, I DON'T KNOW WHICH WING - AND THEN SOMEBODY CAME UP AND SAID WELL WHAT ABOUT THE DRAG? NOW WOULD YOU HAVE MORE LIFT IF THE LEFT WING CAME OFF, WOULD YOU HAVE MORE LIFT ON THE RIGHT WING TO BRING IT BACK UP OR MORE DRAG AND AS YOU SAY - WOULD THE FORCES BE NEUTRAL AND WOULD IT CONTINUE IN THE DIRECTION IN WHICH IT HAD STARTED? IT IS VERY DIFFICULT TO SAY BECAUSE THE FORCES ARE GOING TO CHANGE THE MINUTE ..... THE RIGHT WING WOULDN'T LAST VERY LONG, YOU FELLOWS HAVE NOTED IT - IT CAME APART VERY SOON AFTER THE LEFT WING WENT, SO ALL YOU GOT ON THE RIGHT, THEN, IS A LARGE DEBRIS WHICH IS ESSENTIALLY DRAG. NOW THEN, THE WING THAT CAME OFF WAS THE ONE THAT STAYED INTACT -RIGHT? THAT'S RIGHT.

25X1A THAT THE ONE THAT WAS ON THE AIRPLANE WAS DEBRIS - RIGHT?

THAT THE CNE THAT CAME INTO ALL THOSE PIECES .....

WE CAN STATE THIS THEN, RATHER CONCLUSIVELY, THAT WHICHEVER WING IT WAS, THE ONE THAT CAME OFF IS THE ONE WHICH REMAINED INTACT.

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

NIGHI.

25X1A

25X1A

25X1A

25X1A

25X1A

25X1A

THING THAT CAME OFF WAS THE WING - THE TAIL WAS INTACT - EVERY-THING WAS JUST NORMAL EXCEPT THAT WING WAS COMING OFF AND THEN IT HAPPENED.

25X1A

I WOULD SAY ABOUT THE DISINTEGRATION - I MIGHT ADD, I HAVE MADE A SMALL WAGER THAT THE MAN DID NOT EJECT BECAUSE THIS DISINTE-GRATION - I DID NOT SEE HIM GET OUT BEFORE THE DISINTEGRATION -AND I SAW (AS I MENTIONED EARLIER) ONLY ONE PIECE - LARGE PIECE BESIDES THE WING, AFTER THE WING HAD LEFT, AND THAT WAS THE ENGINE, AND I WAS SURE THAT THE MAN JUST DID NOT - THERE WAS NOTHING LEFT OF ANY OF IT.

25X1A	Approved For Release 2002/06/18 : CIA-RDP,74B00447R000100010065-0Page 108
	COULD HE HAVE EJECTED FROM THE RAILS? AT THE - IF THE PARTS
	CAME OUT FROM AROUND HIM AND HE HAD ALREADY STARTED HIS
	PROCEDURE - WOULD IT STAY TOGETHER TO WHERE THE SEAT WOULD
	KICK OFF THE RAILS WITH A ROCKET OR WHAT'S HE GOT TO KICK IT OFF
	WITH?
	COMMENT:
	HE THINKS HE GOT OUT ALRIGHT UNDER FAIRLY NORMAL EJECTION.
25X1A	THE CANOPY
	WHAT POSITION DOES HE THINK HE WAS IN WHEN HE EJECTED?
25X1A	
25X1A	HE DOESN'T, HE DOESN'T RECALL THAT,
25X1A	HE WAS KNOCKED AROUND QUITE A BIT.
25X1A	OII I THINK - WHAT HIS OWN ORIENTATION?
	L
	STIRRUPS AND GET HIS HANDS - MOVE HIS HANDS SO HE HAD - HE FINALLY
	DEDUCED, I THINK, THAT HE THOUGHT THAT HE WAS FAIRLY NEARLY LEVEL
	, , , , , , , , , , , , , , , , , , , ,

AT LEAST UPRIGHT

UNKNOWN:

A. [1] ( ) [1] [1]

UPRIGHT POSITION AS APPOSED TO BEING ON HIS BACK.

COMMENT:

THIS IS MY OPINION OF LISTENING TO IT THIS MORNING - IN FACT I'LL RUN THIS TAPE FOR YOU GENTLEMEN. I THINK YOU OUGHT TO HEAR IT AFTER WE GET THROUGH HERE, OK. AND I THINK YOU WILL BE INTERESTED IN IT. BUT MY IMPRESSION OF LISTENING TO THE TAPE - HE WAS - AT LEAST HE WAS NOT UPSIDE DOWN. I DON'T THINK HE KNOWS WHETHER HE WAS IN THIS POSITION OR THIS POSITION OR THIS POSITION OR THIS POSITION BUT I DON'T THINK - AH, I THINK HE KNOWS PRETTY CONCLUSIVELY HE WASN'T LIKE THIS.

25X1A

WELL, IF HE EJECTED, I MEAN THE TOPIC IS - I SAY IF HE EJECTED THEY BET ON WHETHER HE DID EJECT OR WHETHER IT CAME OUT AND THEN
HE JUST OPENED THE THUTE. BUT IF HE EJECTED, HE WOULD HAVE
PROBABLY EJECTED - IF WHAT THEY SAY IS RIGHT, HE WAS IN THIS
POSITION, IF HE EJECTED HERE, I DON'T THINK THEY WOULD HAVE SEEN
HIM EJECT - IN OTHER WORDS

.UNKNOWN:

25X1A

PRIOR TO THE DISINTEGRATION?

;

ALL HIS WING - AND HE EJECTED AND DISINTEGRATION TOOK PLACE ABOUT THE SAME TIME. AND THE COPILOT SAYS "IT'S DISINTEGRATING" AND OH, WITHIN TWO SECONDS, THE BOOM OPERATOR SAYS - I HAVE THE PIECES IN SIGHT. THE PILOT, HE'S RIGHT IN WITH THE PIECES.

## Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065g0 110

	QUESTION:
25X1A 25X1A	MAY I ASK YOU THIS WAS HE RIGHT SIDE UP WHEN YOU SAW HIM?
20/(1/(	
	NO SIR, HIS A - APPARENTLY AS I LOOK AT IT NOW, HE WAS IN HIS SEAT
	QUESTION:
25X1A	WELL, WAS HE UPSIDE DOWN OR RIGHTSIDE UP?
	WELL, HIS BACK WAS TO ME AND HIS FEET WAS EITHER DRAWED UP OR IN
	SOMETHING.
	QUESTION:
25X1A	WELL, WAS HE TRAVELING AWAY LIKE THIS?
25 <u>X1</u> A	RIGHT SIR, EXCEPT HE WAS MORE, HIS BACK WAS ALMOST RIGHT TO ME.
25X1A	THEN HIS HEAD WAS UP?
25X1A	YES, HE WAS FACING AWAY FROM ME.
25X1A	WELL, HE WOULD STILL BE IN HIS SEAT EVEN AFTER HE EJECTS.
	JUST LIKE HE WAS IN A CHAIR, SITTING DOWN, HIS BACK WAS TO ME.
	UNKNOWN:
25X1A	AT THAT TIME WERE YOU IN TURN?
	NO. NOT WHEN HE SAW IT BECAUSE AS SOON AS I THRNED HE LOST HIM

Approved For Release 2002/06/18: CIA-RDP74B00447R000100010065-0

### Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065Page 111

25X1A	
	I DON'T SEE WHERE HE COULD HAVE EJECTED DOWN BECAUSE HE WAS
	OFF THE RIGHT WING, AND HE EJECTED DOWN I WOULD NEVER HAVE SEEN
	HIM UNTIL I PICKED HIM UP FURTHER DOWN - BECAUSE HE CAME RIGHT
	ACROSS LEVEL WITH ME - WITH MY BOOM OPERATORS WINDOW, WHEN I
25X1A	FIRST PICKED HIM UP.
25X1A	
	STATED, THAT HE ESTIMATED THAT HE WAS POSSIBLY 1,000 FT
25X1A	ABOVE YOU.
	·

SOMEWHERE BETWEEN 500 AND 1,000.

25X1A

THIS IS WHAT I SAID. I DON'T KNOW HOW FAST IT CLIMBS. THE PERIOD OF TIME WAS COUPLE OR THREE SECONDS OR FIVE SECONDS. WHO KNOWS AT THIS TIME EXACTLY TO HIT YOUR WATCH AND SAY -- NOW, THERE'S ONE THING I WILL SAY - MY INITIAL STATEMENT THAT I MADE AND CHANGED; I SAID THAT THE DISINTEGRATION TOOK PLACE AT 1822 ZULU AND THEN THE NAVIGATOR HAD IT LOGGED AND SO I SAID, WELL, THERE'S FOUR MINUTES DIFFERENCE - I'LL USE YOUR TIME BECAUSE I DON'T REALLY KNOW. BUT MY OWN PERSONAL IMPRESSION WAS FOUR MINUTES LATER THAN WHAT I SAID ON THE ORIGINAL TAPE AND WHAT I HAVE IN THE STATEMENT THERE. AND I UNDERSTAND THAT HE THINKS THAT THE -- IT BROKE UP AT 1822 ZULA, 1022 LOCAL, WHICH IS WHAT I SAID, ALTHOUGH HE HAS IT LOGGED IN - HE HAS A FIX LOGGED AT THAT TIME AND THATS

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

I MIGHT ADD THAT TO MY KNOWLEDGE I WAS FAIRLY - FEEL I'M FAIRLY ACCURATE ON THE TIME BECAUSE I WAS A LITTLE PRESSED ABOUT MAKING A 180 DEGREE TURN. WE HAD INSTRUCTIONS NOT TO GO SOUTH OF THIS POINT, I THINK IT WAS 40 NAUTICAL MILES NORTH OF PALMDALE, AND SO I HAD A TURNING POINT THAT I ESTIMATED WE WOULD BE AT THAT TURNING POINT TO HEAD BACK AT 16 AFTER THE HOUR - AND WHEN WE HADN'T, I WAS PRESSING HIM - "LET'S GET GOING, LET'S GET GOING".

I'M WATCHING MY WATCH AND WATCHING AND TRYING TO GET OUT OF THERE, AND FINALLY HE WAS THROUGH AND I GOT UP AND I KNEW WE WERE GOING TO MAKE OUR TURN WITHIN TIME BEFORE WE PASSED THAT POINT.

25X1A

THE MANUAL THAT I HAVE ON THE AIRCRAFT SAYS MAXIMUM SPEED IS AROUND 220. IS THAT FAIRLY ACCURATE?

25X1A

WELL, THE MAXIMUM WE'RE ALLOWED 240 IN THE GUST CONTROL AND 220 IN THE FAIRED CONDITION. THE GUST CONTROL IS WHEN THE FLAPS AND THE AILERONS MOVE UP TO RELIEVE LOAD FROM THE WINGS AND WE ALWAYS REFUEL WITH THE FLAPS AND THE AILERONS IN THE GUST POSITION. THE FLAPS MOVE UP 4 DEGREES AND THE AILERONS MOVE UP 10 DEGREES. THIS RELIEVES LOADS SO IF WE ENCOUNTER ANY TURBULENCE, THEN WE ARE IN THE BEST CONFIGURATION FOR IT. THOSE ARE - AS YOU REALIZE IT, A VERY FRAGILE AIRPLANE AND THOSE ARE VERY STRICT LIMITS WITH US. BUT WE OBVIOUSLY WISH TO GET OUR REFUELING SPEED DOWN AS

TO THE

	Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0 ${ m Page-113}$
	LOW AS WE POSSIBLY CAN TO RELIEVE STRESSES ON THE AIRPLANE AND
	WE ALSO USE THE GUST CONDITION. THEREFORE, IT WAS ORIGINALLY
	220 KNOTS, I BELIEVE - OUR REFUELING, AND WE WANTED TO BRING IT
	DOWN AND THE TANKER CREW SAID, WELL, WITH THIS PARTICULAR LOAD
	200 IS THE ABSOLUTE MINIMUM TO BY FLYING AT 35,000 FEET.
25X1A	
	THAT'S WITH 220,000 POUND TANKER GROSS WEIGHT - RIGHT?
25X1A	
25X1A	I CAN'T BE CERTAIN.
25X1A	I'M ALMOST CERTAIN. BECAUSE WE WERE WELL BELOW THAT
a- /	IT JUST NATURALLY HAS TO VARY - FOR EXAMPLE YOU'RE OVERWEIGHT
	SOMETIMES OR WHERE EVER WE'RE AT YOU'RE NOT LOW ENOUGH - YOU
25X1A	JUST CAN'T GET TO 200.
	THAT'S RIGHT.
	UNKNOWN:
	HE WAS - AT THE SPEED YOU'RE TALKING ABOUT, THAT YOU ARE KINDA
25X1A	CONCERNED ABOUT - HE WAS WITHIN THE ENVOLOPE.
25X1A	YEAH, WELL I'M - I WAS JUST WONDERING

IN THE CONFIGURATION HE WAS IN, HE WAS ALLOWED TO GO TO 240 KNOTS.

25X1.	Α
-------	---

20/1/1/	Approved For Release 2002/06/18 : CIA-ROP74B00447R000100010065-0 Page 114
	WELL, HE WAS WELL UNDER THAT - WELL, I MEAN THIS WAS - IT'S DEFINITE
	THAT HE WAS UNDER, WELL UNDER 240 BECAUSE IF HE HADN'T BEEN HE
25X1A	WOULD HAVE LEFT ME.
	·
	HE NEVER GOT HIS ACCELERATION AND THE CLIMB WAS NORMAL AND
25X1A	WASN'T ABOUT IT - BANKING -
•	
	YOU SEE WE'RE LIMITED BY TURBULENCE AS WELL - TO GIVE YOU AN
	INDICATION IF WE HIT MODERATE TURBULENCE, THEN OUR LIMITS / RE
	BROUGHT DOWN RESPECTIVELY FROM 240 TO 170 AND FROM 220 TO 150.
	THEN WE'VE GOT 150 IN FAIRED CONDITION AND 170 KNOT LIMIT IN GUST
	CONDITION. SO YOU SEE IF WE HIT ANY TURBULENCE UP THERE EVEN AT
05)/44	200 KNOTS, EVEN IN THE GUST POSITION, MODERATE TURBULENCE WE
25X1A	ARE, STRICTLY SPEAKING, EXCEEDING THE -1 LIMITS.
	DESIGN LIMITS. DASH ONE.
	UNKNOWN:
	HAVE YOU EVER FOLDED A WING IN THIS FASHION?
25X1A	,
	NO. FIRST ONE I'VE EVER SEEN FAIL WAS
057/44	UNKNOWN:
25X1A	WE'VE HAD A WING FOLD AFTER A TAIL COME OFF.
-	25X1A
	THE ONLY ONE WHERE THE TAIL DIDN'T COME OFF FIRST WAS
	OVER Approved With Release 2002/06/18: FCDA; RDP 7/41880 4/47 R800 1.000 17065-10 JETS ON THE

25X1A	Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0 Page 116
25X1A	UNDER A G LOAD - AN EXCESSIVE G LOAD, IN THE GÜST.
	YES, I THINK.
	UNKNOWN:
25X1A	HOW ABOUT A NEGATIVE G LOAD? SAME PLACE?
	SAME GENERAL AREA.
	UNKNOWN:
	THE AIRPLANE IS TURNING TO THE RIGHT IT LOOKS LIKE IT WOULDN'T HAVE
	A NEGATIVE G LOAD ON IT. IT CERTAINLY WOULD NOT HAVE MUCH OF A
	LOAD ON IT IN A RIGHT TURN IF IT'S THE LEFT WING THAT FAILED.
	UNKNOWN:
	IT WOULD HAVE LOWER LOAD WOULDN'T IT?
25X1A	
25X1A	THATS THE WING THAT'S GOT THE LIFT.
	A LITTLE MORE LIFT.
25X1A	
25X1A	THE LEFT WING SOULD GET AN INCREMENT OF LOAD INCREASE.
	RIGHT TURN - THE LEFT WING SHOULD HAVE THE LIFT.
	UNKNOW::
	THE LEFT WING, IT WOULDN'T HAVE THE LIFT ON IT.
~	UNKNOWN:
	$^{ m WELL}$ , Approved for Release 2002/06/18 TCIA-RDP74B00447R000100010065- $^{ m AILS}$ TOO.

	Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0 $^{ m Page-117}$
25X1A	
	ONCE HE GETS HIS INITIAL TURN IN, IF HE HAD HIS TURN IN THE AILERON
	AND NO FORCE IN THE AILERON AT THAT TIME, THEN THERE WOULDN'T
	BE THAT MUCH LOAD ON IT.
	COMMENT:
	NO THERE WOULD BE LESS LOAD ON IT.
	COMMENT:
25X1A	IT HAS BEEN ESTABLISHED BY THESE WITNESSES HERE THAT HE
	ESTABLISHED DEFINITELY TWO DIFFERENT MANEUVERS HERE - ONE WAS
	CLIMB AND THEN ESTABLISHED THE TURN SO IT WASN'T A ROLLING
25X1A	PULLOUT - THAT TYPE OF MANEUVER AT ALL.
	I PERSONALLY BELIEVE THAT IF - THIS IS JUST OPINION - NOW IF HE'D
	HAVE JUST CONTINUED HIS CLIMB - STRAIGHT AND LEVEL - I THOUGHT
	EVERYTHING WOULD HEVE WORKED PERFECTLY. IT SEEMED JUST THE
	INSTANT THAT HE STARTED TO BANK TO THE RIGHT - LET'S SEE, THATS
25X1A	RIGHT - BANK TO THE RIGHT THAT IT JUST BUCKLED THAT WING RIGHT OVER.
	HOWEVER, I SAW THE FUEL SPRAY, IF THIS IS CONNECTED WITH IT. I SAW
25X1A	THE FUEL SPRAY BEFORE THE TURN.
25X1A	BEFORE HE BANKED?
	,
	THATS RIGHT.

25X1A	Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065F0age 118
	I THINK THATS A KIND OF A PERTINENT FACT. FUEL SPRAY COMING OFF
	FROM SOMEPLACE. WE SEEM TO HAVE DIFFICULTY ESTABLISHING WHERE
25X1A	IT WAS COMING FROM AND I IMAGINE THIS IS DEPTH PERSPECTIVE.
	I JUST = MAY I ASK THE COPILOT IF HE NOTICED ANYTHING COMING FROM
	THE VERY TIP AT ALL.
25X1A	
	I HEARD YOU COMMENT ON THAT, I DIDN'T SEE ANYTHING THAT YOU WOULD
25X1A	CALL VAPOR TRAILS - I JUST REMEMBER THE FUEL.
	BUT YOU COULDN'T RECALL WHETHER IT WAS JUST PRIOR OR DURING THE
25X1A	ACTUAL WING BUCKLING THAT THIS?
	I DO BELIEVE THAT THERE WAS VAPOR COMING OUT IN HIS CLIMB STRAIGHT
	UP BUT I HAVE SEEN THIS HAPPEN BEFORE AND I HAVE SEEN ONE TAKEOFF
	FROM WAKE ISLAND AND FUEL COME OUT OF IT.
25X1A	
	I THINK IT'S TIP VORTICLES TYPE AFFECT - I MEAN, THE COMPRESSION
	AFFECT OF THE RAPID PULLUP - THE SAME THING YOU SEE IN FIGHTERS
	WHEN THEY COME UP - THE STUFF COME OFF OF THEIR WINGS WHEN THEY
	COME UP AND THEN START BENDING IT BACK AROUND.

25X1A	Approved For Releas	e 2002/06/18 : CIA-RDP74B	(1) ((1)) (1) /18: CIA-RDP74B00447R000100010065-Dage 119	
25X1A	I'D LIKE TO A <b>S</b> K	A QUESTION,	WOULD YOU CONSIDER THE	
25X1A	VAPOR TRAILS TO BE M	ILD- MODERATE- O	R VERY HEAVY?	
	I WOULD SAY ABOUT MO	ODERATE.		
25X1A	:			
25X1A	MODERATE?			
	INITIALLY WHEN HE CA	ME IN HE HAD A CO	N OF ABOUT, A GUESS, OF ABOUT	
	A MILE AND A HALF, D	ISSIPATING AFTER T	HAT. I MEAN, IT WASN'T A CON	
	THAT STAYED. IT WAS	S NON-PERSISTENT.	THE CON, YOU'RE TALKING ABOUT	
25X1A	THE ENGINE CONTRAIL			
	YES.	•		
25X1A				
25X1A	THAT	S THAT HE COULD ST	TILL SEE THE CONTRAILS FROM	
	THE ENGINE, I MEAN F	ROM THE AIRCRAFT	•	
25X1A	·			
	HAVE YOU EVER SEEN.	ANY VORTEX TRAILS	FROM THE TIP OF THIS, SHU?	
25X1A				
25X1A	NO.		•	
	:			
25X1A	UNDER NAY CONDITION	S?		
	:			
	NO. YOU'RE NOT NOR	MALLY LOOKING BAC	CK SO THE ODDS ARE YOU	
	WOULDN'T ANYTOW.  Approved For Release	e 2002/06/18 : CIA-RDP74B	00447R000100010065-0	
	Apploton I of Iteleas			

25X1A	Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0 ge 120
25X1A	I MEAN FLYING ALONG SIDE ANOTHER ONE OR MANEUVERING.
	[
25X1A	NO. NOT AT THAT ALTITUDE.
25X1A	PILOT ASKED ME ONE TIME - WAS I HOLDING HIM BACK?
251/4 4	
25X1A	YEAH, HE DID, I REMEMBER THAT.
	AND I TOLD HIM NEGATIVE. BUT HE WAS RIGHT IN THE AREA WHERE YOU
25X1A	GET THAT BOUNDARY.
25X1A	BOW WAVE.
	AND I JUST PASSED IT OFF IN MY MIND HE WAS RIGHT IN THAT POSITION
	AND I FIGURED THATS WHAT IT WAS. BUT HE WAS ON THE BOOM, WE WAS
	IN CONTACT, AND USUALLY THE GUYS NEVER MENTION IT ONCE THEY ARE
	IN CONTACT - BUT HE DID MENTION THAT. HE DID ASK ME IF I WAS HOLDING
	UHM BACK.
25X1A	
	WE HAD BOW WAVE IN THE TANKER ON THE FIRST THREE CONTACTS, YOU
	KNOW, THE PORPOSING. AND NORMALLY IN THIS TYPE AIRCRAFT, WITH
	THIS TYPE AIRCRAFT IT'S WHEN HE IS HIGH IN THE ENVELOPE THAT HE
	CAN DO THIS BECAUSE EACH MOVEMENT OF HIS CONTROLS AFFECTS MY
	CONTROLS AND IT TRYS TO PITCH IT OVER AND THE AUTOPILOT BRINGS

25X1A

NORMALLY .... THE ONLY TIME I NOTE ANYTHING IS WELL - IF ITS UNUSUAL

UNKNOWN:

WELL. WERE YOU AT YOUR MAXIMUM LENGTH? WHAT WAS THE LENGTH OF YOUR PROBE THE FIRST TWO AS AGAINST THE LATTER ONES? AND THE ANGLE OF IT BEING WHERE THE .....

25X1A

AT THE TIME HE ASKED ME WAS I HOLDING HIM BACK, HE WAS A LITTLE LOW. HE WAS WITHIN THE LIMITS, BUT HE WAS JUST A LITTLE LOWER.

## Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-9c 122

	UNKNOWN:
25X1A	DID HE EVER COME TO THE END OF YOUR LIMITS, AZIMUTH OR VERTICAL?
25X1A	NO, HE NEVER DID ANYTHING. JUST A PERFECT, REFUELING.
	THERE WAS SOME MENTION MADE THAT THERE WAS A JET STREAM AT 28.
	JUST WONDERED IF IT'S CONCEIVABLE THAT POSSIBLY YOU MIGHT HAVE SEEN
	SOMETHING JUST PRIOR TO THE BREAKUP THAT WOULD INDICATE THAT
	THE TURBULANT CONDITION MIGHT HAVE CHANGED WITHIN A 1,000 FEET
25X1A	ABOVE YOUR
	THE WEATHER WAS - HIGH ALTITUDE WEATHER WAS PERFECTLY CLEAR.
	NO INDICATION OF ANYTHING. I MEAN, WISPY CLOUDS AND SOFORTH
	THAT YOU WOULD GET WITH HIGH SPEED WINDS OR POSSIBLY SHEAR?
25X1A	NO INDICATION.
	ANY TURBULENCE?
25X1A	
25X1A	NO.
25X1A	IS IT YOUR BELIEF THAT THAT JET STREAM WASN'T THERE AS FORECAST?
	WELL, THE JET STREAM THAT I MENTIONED - I'LL TELL YOU - PRIOR TO
	LEAVING BEAL, - I WAS IN THE WEATHER STATION AND TALKED TO THEM
	AND ASKED HIM WHAT THE WEATHER WAS YESTERDAY AT 1800 ZULU IN THE
	LOS ALAGOROVES HODRESERSES 2002/06 18: CHARDPA 4B00447 RD00100010005 FOT ALL THE CHART

AND SAID THEY HAD A JET STREAM AT ABOUT 28,000 FEET WHICH IS THE

CORE OF THE JET. ABOVE IT, WHICH AT 35,000 FT HIS WINDS I BELIEVE NOW, TO THE BEST OF MY KNOWLEDGE, HE SAID 280 AT ABOUT 70 IS THE DEGREE BUT AT 28,000 THEY WERE AT ABOUT 100 SOME KNOTS. AND SO THIS WOULD INDICATE WE WERE WELL ABOVE ANY OF THE JET. MY WINDS, I GAVE YOU WERE 260 AT 60 OR 265 AT 60. ABSOLUTELY NO TURBULENCE AND JUST TO DEFINITELY CLEAR SOMETHING UP, WHEN HE STARTED HIS CLIMB, PRIOR TO THE LEFT WING COMING OFF, I DEFINITELY SAW A VAPOR COMING FROM THE WING - WHEREABOUTS IN THE WING AND HOW STRONG OR HOW LONG I WOULDN'T DEFINITELY QUOTE ON THAT.

25X1A

\_\_\_\_\_

25X1A AND THIS WAS IN THE CLIME DEFORE THE TURN?

25X1A

YES.

25X1A

HAS MADE SOME PRETTY POSITIVE OBSERVATIONS
ABOUT THE VAPOR. I JUST WONDER IF WE COULD GO OVER IT AGAIN.
HE WAS FLYING IN FORMATION ABOUT LEVEL ATTITUDE, SLIGHTLY
FORWARD OF THE TANKER WING - ABOUT 200 FT. OUT AND WENT INTO A
CLIMB, AND IT WAS ABOUT THIS TIME I BELIEVE, YOU SAID YOU SAW THE
VAPOR. AND THEN HE WENT INTO A ROLL - THAT'S WHEN THE WING
FOLDED UP.

25X1A

SHORTLY AFTER HE ENTERED THE ROLL, THE WING SEPARATED - WAS STARTING TO COME OFF.

25X1A	Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0
	BUT THERE WAS A DEFINITE TIME INTERVAL WHEN HE WENT INTO A CLIMB
	ME SAW SOME VAPOR.
25X1A	
	THATS RIGHT, THE INITE'L ACCELERATION - AND IT ALMOST CEASED AND
25X1A	THEN HE STARTED THE BANK.
	HE WAS GOING UP LIKE THIS AND THEN HE WENT INTO A ROLL AND THEN
25X1A	THE WING FAILED?
	· ·
	THATS RIGHT.
25X1A	
	AND YOU FEEL FAIRLY CERTAIN THAT THE FUEL VAPOR YOU SAW WAS DOWN
25X1A	IN THIS REGION.
	i:
	IT WAS - THATS RIGHT. I'M NOT SURE - THE VAPOR AS IT CAME OUT GOT
25X1A	LARGER.
25X1A	BUT IT WAS DOWN IN THE WING ROOT IN THE FUSELAGE AREA?
	IT WASH'T BEHIND THE WING. YOU SEE THIS PART RIGHT HERE? IT WAS
	ANYWHERE BEHIND THAT AND IT COULD BE - I BELIEVE IT WAS ON THE
	BODY OF THE AIRCRAFT AND NOT ON THE WING, THAT'S WHAT I THINK.
	AND WHERE THE WING BROKE WAS RIGHT WHERE THIS - SO IT HAD TO BE
	ALMOST ONE AND THE SAME PLACE. IT MIGHT HAVE BEEN RIGHT AT THE

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0

	Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-Dage <sup>125</sup>
	JOHLT, THERE, BECAUSE THE WING BROKE RIGHT WHERE THIS VAPOR
25X1A	WAS COMING FROM - THAT'S WHERE I FIRST NOTICED AN OPENING.
	COULD YOU TELL CONCEIVEABLY, THE WING TOOK PART OF THE FUSELAGE
25X1A	WITH IT WHEN IT BROKE?
	NO SIR, I DON'T THINK IT DID. I THINK THE WING, THE WHOLE WING RIGHT
	THERE - IT JUST TOOK THAT WING OFF AND BENT IT BACK OVER AND IT
25X1A	ALL WENT BY ITSELF AND NO PART OF THE FUSELAGE.
	I THINK WHAT HE'S TRYING TO SAY IS, IT DIDN'T TAKE ANY OF THE SKIN
	THE SKIN PORTION OF THE FUSELAGE, IN OTHER WORDS - IT BROKE CLEAN.
25X1A	
25 <b>XT</b> A	THATS RIGHT
	AS THIS MODEL IS MADE AT THE JOINT.
25X1A	,
	THATS RIGHT.
25X1A	
	AND THE IMPLICATION OF THAT, I GUESS WOULD BE, THAT THERE WAS
	EVIDERTLY A RUPTURE IN THE WING LOWER SURFACE FROM WHICH FUEL
	VAPORS MIGHT HAVE BEEN STREAMING, RIGHT DOWN NEAR THE WING ROOT,

WHEN THEY APPEARED TO BE COMING OFF THE FUSELAGE.

25X1A	Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-0
	COULD VERY WELL BE. BECAUSE I WOULDN'T, ALL I COULD SEE WAS THE
	VAPOR. I COULDN'T SEE AN OPENING UNTIL THE WING SEPARATED - UNTIL
	THE WING SEPARATED, I DIDN'T KNOW ANYTHING WAS WRONG. SO I
	COULDN'T TELL WHERE EXACTLY THE VAPORS WERE COMING FROM.
25X1A	
	WE DON'T HAVE ANY OPENINGS IN THE FUSELAGE DO WE BILL?
25X1A	
	DO YOU DETERMINE WHETHER IT WAS THE SOURCE OF THIS VAPOR WAS
	AHEAD OF THE TRAILING EDGE OF THE WING OR NOT?
25X1A	
25X1A	IT WAS AHEAD OF THE TRAILING EDGE.
25 <b>X1</b> A	DEFINITELY AHEAD, THEREFORE IT MUST HAVE BEEN FROM UNDERNEATH.
	THATS RIGHT.
	UNKNOWN:
	AT THE TIME THE WING BROKE UP, DID YOU NOTICE ANY INCREASE OR ANY
	SUDDEN CLOUD OF VAPOR?
25X1A	
	NO I DIDN'T. IT MIGHT HAVE BEEN, BUT I DIDN'T NOTICE ANY. I THINK
	IF THERE HAD OF BEEN A DIG VAPOR CLOUD THERE, I WOULD HAVE
	NOTICED IT- I PRODABLY WOULD HAVE SAID IT WAS SMOKE OR SOMETHING,

Approved For Release 2002/06/18 : CIA-RDP74B00447R000100010065-6 Page 127

BUT IT WAS UNUSUALLY CLEAR, THERE WAS NOTHING LIKE SMOKE OR FIRE OR VAPOR.

25X1A

25X1A

THINK WHAT WOULD OF HAPPENED HERE, GENTLEMEN, IS THAT THE EYES WOULD HAVE BEEN ON THE PIECES, WHEREAS ANYTHING, ANY FUEL THAT CAME OUT FROM THEREON, OR VAPOR THAT CAME OUT, WOULD HAVE BEEN WHIPPED STRAIGHT BACK, WHEREAS THE EYEBALL WOULD BE ON THE MAJOR PORTIONS AND PIECES.

UNKNOWN:

YOU MITHIT PLAY DEAK'S TAPE FOR THE GUYS. THEY MIGHT GET SOME ADDITIONAL INFORMATION ....

YEAH, I'D LIKE TO HEAR THAT TOO.

1 /

INITIALS

DATE

INFORMATION

SIGNATURE

Approved For Release 2000001116:30114-RDP74B00447R000100010005-0

NAME AND ADDRESS

ACTION

COMMENT

REMARKS

TO

le

QUOTE " year d'I likete Manthat too"

CONCURRENCE

FILE

FROM

NAME AND ADDRESS

PHONE NO.

Approved For Release 2002/06/18 : CIA-RDP74B00447R0001000 0065-0

FORM 1582

(40)

# TOP SECRET

### THIS DOCUMENT REQUIRES SPECIAL HANDLING

#### HANDLING PROCEDURES

THIS DOCUMENT CONTAINS INFORMATION REGARDING A HIGHLY CLASSIFIED ACTIVITY. PERMISSION TO TRANSFER CUSTODY, OR PERMIT ACCESS TO THIS DOCUMENT MUST BE OBTAINED FROM THE ORIGINATOR. HAND CARRY PROCEDURES WILL BE APPLIED TO ANY INTER-OFFICE OR INTRA-AGENCY MOVEMENT OF THIS DOCUMENT.

This document contains information referring to Project IDEALIST

Maint

REFERRED TO	RECE/I VED			RELEASED		SEEN BY	
OFFICE	SIGNATURE	DATE T	IME D	ATE	TIME	NAME AND OFFICE SYMBOL	DATE
			-				
	•		1	}			

CLASSIFICATION

TOP SECRET

Joseph 164

25X

7530-633-9673 ENVELOPE PHOTOGRAPHIC NEGATIVE Filed in Section
NoUnit
Date Taken By
Neg. Size 2/4 2/4 Classification.
Location, Altitude, Orientation, Focal Length of Lens, etc., as applicable.  File
*This space for
OFFICIAL NAVY PHOTOGRAPH  APPROPRIATE FILING
COMPLETE TITLE AND DESCRIPTION OF PICTURE  LETTER. (SEE ARTICLE 0700-2 MANUAL OF
(Occasion, action, make, model, type, name, rank, rate, initials, address, serial, etc.)
ART. 342 INCIDENT 3 MAR GE
WING PICTURES
***************************************
***************************************
If released for publication, Officer releasing sign below.
Rank Date

No

7530-633-9673 ENVELOPE PHOTOGRAPHIC NEGATIVE Filed in Section · No....... Unit...... Date Taken...... By..... Neg. Size...... Classification..... Location, Altitude, Orientation, Focal Length of Lens, etc., as applicable. File \* THIS SPACE FOR OFFICIAL NAVY PHOTOGRAPH APPROPRIATE FILING LETTER. (SEE ARTICLE COMPLETE TITLE AND DESCRIPTION OF PICTURE 0700-2 MANUAL OF NAVAL PHOTOGRAPHY) (Occasion, action, make, model, type, name, rank, rate, initials, address, serial, etc.) ARTICLE 342 INCIDENT HAUGER SHOTS If released for publication, Officer releasing sign below. Rank Date

of Alphabetical Print